





report date: 2024-03-28

General information

Make	MERCEDES
Model	E E240 ELEGANCE
Colour	Silver
Year of manufacture	2003
Top speed	136 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	240 Nm at 4.500 rpm
Engine capacity	2.597 cc
Cylinders	6
Fuel type	Petrol
Consumption city	16.2 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.9 mpg
CO2 emission	247 g/km
CO2 label	L



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 2

Date 2022-09-23

Pictures 11

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Date	2021-07-16

Pictures 59

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-07-10
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	21
Total items failed	9

MOT #23	2023-07-11 07:30
MOT test number	257298081428
Result	✓ Passed
Next expiry date	2024-07-10

MOT #	22	2023-06-14 16:09
MOT te	st number	629195908810
Result		× Failed
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail	Nearside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))	

MOT #2	21	2023-01-26 15:57
MOT te	st number	234247553298
Result		× Failed
Fail	Rear fog lamp not working (4.5.1 (a) (ii))	
Fail (ii))	Rear Registration plate lamp inoperative in the case of a single lamp or all lamp	s both lights (4.7.1 (b)
Fail	Offside Rear Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/14



Result

VO52AEC

report date: 2024-03-28

★ Failed

MOT #20 2022-03-12 10:59

MOT test number 601153579586

Result \rightarrow Passed

Advice Offside Front Outer Tyre worn close to legal limit/worn on edge Also tyre wall perished and cut on tread pattern but not showing ply chords (5.2.3 (e))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #19 2021-04-02 15:07

MOT test number 971506272764

Result
✓ Passed

MOT #18 2020-12-16 14:02

MOT test number 500750506787

MOT #17 2019-12-17 12:21

MOT test number 260852181658

Result
✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2019-12-17 12:21

MOT test number 159041887160

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #15		2018-12-14 10:38
MOT test	number	823588681579
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14		2017-12-21 10:41
MOT test	number	559555845506
Result		✓ Passed
Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in e	excessive movement
Advice	Brake Wear Warning On Dash	
Advice	N/S/F Tyre Has A Cut In Outer Sidewall	
Advice	Battery Warning Message On Dash	

MOT #13	2016-12-19 12:43
MOT test number	400224486622
Result	✓ Passed
MOT #12	2015-12-23 09:17
MOT test number	187204000437
Result	✓ Passed
MOT #11	2014-09-15 13:47
MOT test number	717028754263
Result	✓ Passed
MOT #10	2013-09-09 14:09
MOT test number	917512053218
Result	✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #9 2013-09-09 14:09

MOT test number 726572253292

Result X Failed

Pass with rectification

Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)

Pass with rectification

Nearside Front Brake hose has insufficient room to move, resulting in fouling on

any part (3.6.B.4a)

MOT #8 2012-08-20 09:05

MOT test number 579053332254

Result

Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2011-09-01 16:00

MOT test number 727464341268

Result ✓ Passed

Notice Offside and nearside tyres have uneven tread wear (225/5516).

MOT #6 2010-09-07 14:55

MOT test number 203820950272

Result ✓ Passed

MOT #5 2009-09-04 11:15

MOT test number 191457949229

Result
✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/14



MOT #4	2008-09-15 16:09
MOT test number	661109958281
Result	✓ Passed
MOT #3	2007-09-14 08:14
MOT test number	724727357208
Result	✓ Passed
MOT #2	2007-09-13 16:48
MOT test number	334106457298
Result	× Failed
Fail Hazard warning lamps not flashing in phase, with ignition on (1.4.B.1f)	

MOT #1	2006-11-02 14:02
MOT test number	601676106335
Result	✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
venicle class	40
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra MERCEDES salvage check



CarCheck.co.uk

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downlo	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NK NA
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles	
Mileage registrations	22	
First mileage registration	2003-01-10	
Last registration	2023-07-11	
Complete history	See info	



2003-01-10	13 mi
2006-11-02	22.655 mi
2007-09-13	29.171 mi
2007-09-14	29.171 mi
2008-09-15	37.510 mi
2009-09-04	43.250 mi
2010-09-07	48.608 mi
2011-09-01	52.475 mi
2012-08-20	56.585 mi
2013-09-09	59.994 mi
2014-09-15	64.849 mi
	11.777 es
	11.777 es
	11.777 es
	9.70 es
	11.777 es
	9.70 es
	11.777 es
	11.777 es
	11.777 es
	11.777 es
	11.777 es
	2006-11-02 2007-09-13 2007-09-14 2008-09-15 2009-09-04 2010-09-07 2011-09-01 2012-08-20 2013-09-09 2014-09-15

More info >

CarCheck.co.uk page 13/14



Additional information

Engine number 11291331355992

CarCheck.co.uk page 14/14