



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2005
Top speed	143 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-11
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-21
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	22
Total items failed	6

MOT #20	2024-03-22 12:35
MOT test number	308060374926
Result	✓ Passed
Next expiry date	2025-03-21
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Undertrays fitted not allowing full inspection of some components
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #19**

2024-03-12 09:17

MOT test number

397335509723

Result

✗ Failed

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Advice** Undertrays fitted not allowing full inspection of some components**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #18**

2022-12-19 12:18

MOT test number

410582291189

Result

✓ Passed

MOT #17

2021-12-16 09:11

MOT test number

539272210386

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))**MOT #16**

2021-09-28 11:02

MOT test number

254593866769

Result

✗ Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Rear Exhaust system insecure support (6.1.2 (a))

**MOT #15** 2020-10-13 09:34**MOT test number** 657614085307**Result** ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower front arm inner bush (as marked) (5.3.4 (a) (i))

MOT #14 2019-10-14 13:23**MOT test number** 654592796784**Result** ✓ Passed

Advice Rear Inner Brake pad(s) wearing thin both rear inner pads (1.1.13 (a) (ii))

MOT #13 2018-10-04 13:51**MOT test number** 649708647966**Result** ✓ Passed**MOT #12** 2017-10-14 12:10**MOT test number** 754405960491**Result** ✓ Passed**MOT #11** 2016-09-27 11:58**MOT test number** 449978499054**Result** ✓ Passed

Advice Both front and nearside rear tyres perished and offside rear on 3mm

Advice Exhaust bracket broken unlikely to fall off

MOT #10 2015-09-28 13:10**MOT test number** 390719077153**Result** ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2014-10-11 15:58**MOT test number** 629234684240**Result** ✓ Passed**MOT #8** 2013-10-16 10:46**MOT test number** 377849783468**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #7** 2013-10-16 10:46**MOT test number** 236499883268**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2013-04-13 10:36**MOT test number** 757713603195**Result** ✓ Passed**MOT #5** 2012-04-10 14:18**MOT test number** 405041102157**Result** ✓ Passed**Advice** Centre Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #4** 2011-04-14 12:55**MOT test number** 545544001127**Result** ✓ Passed



MOT #3	2010-04-09 12:36
MOT test number	963449690060
Result	✓ Passed

MOT #2	2009-04-15 15:39
MOT test number	371485609166
Result	✓ Passed
<div>Notice Offside front tyre worn on the inner edge</div>	

MOT #1	2008-04-15 09:44
MOT test number	404526008117
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
21 March 2025

Tax status	Valid until 1 December
Days left	215
MOT expiry date	21 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-29
Last registration	2024-03-22
Complete history	See info



Registration #1	2005-03-29	20 mi
Registration #2	2008-04-15	23.890 mi
Registration #3	2009-04-15	27.376 mi
Registration #4	2010-04-09	31.616 mi
Registration #5	2011-04-14	35.807 mi
Registration #6	2012-04-10	38.993 mi
Registration #7	2013-04-13	42.504 mi
Registration #8	2013-10-16	44.303 mi
Registration #9	2014-10-11	46.652 mi
Registration #10	2015-09-28	48.199 mi
Registration #11	2016-09-27	49.453 mi
Registration #12	2019-05-29	51.577 mi
Registration #13	2019-05-29	51.577 mi
Registration #14	2019-05-29	51.577 mi
Registration #15	2019-05-29	51.577 mi
Registration #16	2019-05-29	51.577 mi
Registration #17	2019-05-29	51.577 mi
Registration #18	2019-05-29	51.577 mi
Registration #19	2019-05-29	51.577 mi
Registration #20	2019-05-29	51.577 mi
Registration #21	2019-05-29	51.577 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430552799