





report date: 2024-03-29

# General information

Make	FORD
Model	MONDEO TITANIUM X TDCI
Colour	White
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Semi-Automatic

# Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history


# Entry 1


Date 2021-10-30

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

# MOT history

MOT expiry date	2024-10-28
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	29
Total items failed	0

MOT #12	2023-10-25 11:43
MOT test number	405490322454
Result	✓ Passed
Next expiry date	2024-10-28
Advice Offside Front head lamp misted , affecting beam pattern	
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))	
Advice Offside Front drivers seat base worn	
Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))	

MOT #11	2022-10-29 09:33
MOT test number	399721647804
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #10** 2021-10-16 14:41 **MOT** test number 484585820239 Result ✓ Passed Minor Nearside Front Tyre obviously under inflated (5.2.3 (I)) **Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) Advice Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i)) Advice Advice Oil leak, but not excessive (8.4.1 (a) (i))

2021-10-16 11:47 **MOT #9** 412447391029 **MOT test number** Result × Failed **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii)) **DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick both sides (1.1.13 (a) (ii)) **Advice** Rear Brake disc worn, but not excessively both have slight lip to edges (1.1.14 (a) (i)) **Advice** Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i)) Minor Nearside Front Tyre obviously under inflated (5.2.3 (I)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Advice Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8		2020-10-10 10:39
MOT test	number	122722773407
Result		✓ Passed
Advice	Rear brake pads getting low	
Advice	Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #7		2019-03-22 11:54
MOT test	number	482678747816
Result		✓ Passed
MOT #6		2018-03-21 10:51
MOT test	number	108656157865
Result		<b>✓</b> Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5		2017-03-17 10:49
MOT test	number	540044667318
Result		<b>✓</b> Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2016-03-18 13:58
MOT test number	518072559400
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3	2015-04-01 10:04
MOT test number	637551895036
Result	✓ Passed
MOT #2	2014-04-04 10:42
MOT test number	637024994031
Result	✓ Passed
Notice Front tyre,s wearing on inside edge	

MOT #1	2013-03-06 17:10
MOT test number	415315363010
Result	<b>✓</b> Passed
Notice Nail in nearside rear tyre	

CarCheck.co.uk page 6/13



GL10FNF report date: 2024-03-29

# Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	28 October 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

# Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



GL10FNF report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

**GL10FNF** 

report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this FORD had different number plates.

CarCheck.co.uk page 10/13



**GL10FNF** report date: 2024-03-29

## Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-08-31
Last registration	2023-10-25
Complete history	See info



Registration #1	2010-08-31	20 mi
Registration #2	2013-03-06	21.718 mi
Registration #3	2014-04-04	29.360 mi
Registration #4	2015-04-01	35.072 mi
Registration #5	2016-03-18	41.138 mi
Registration #6	2017-03-17	46.554 mi
Registration #7	2018-03-21	50.423 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		0.00 44
Registration #13		11.777 mi

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-29

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2078 mm
Height	1512 mm
Length	4830 mm
Wheel base	2850 mm
Kerb weight	1606 kg
Max. allowed weight	2335 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/1