



report date: 2024-03-28

General information

Make	VOLVO
Model	C70 D SPORT
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	46.3 mpg
CO2 emission	161 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-18
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-13
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	25
Total items failed	7

MOT #19	2023-06-14 12:50
MOT test number	575805712725
Result	✓ Passed
Next expiry date	2024-06-13

MOT #18	2022-04-07 11:22
MOT test number	217481088524
Result	✓ Passed

MOT #17	2022-04-07 09:26
MOT test number	219331232828
Result	✗ Failed
<div>MAJOR Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))</div> <div>MAJOR Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))</div>	

**MOT #16**

2021-09-09 12:06

MOT test number

773688253249

Result

✓ Passed

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear arm bush (5.3.4 (a) (i))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear arm bush (5.3.4 (a) (i))

MOT #15

2021-09-09 12:06

MOT test number

938729634964

Result

✗ Failed

- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear arm bush (5.3.4 (a) (i))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear arm bush (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #14

2020-11-23 12:53

MOT test number

485869789462

Result

✓ Passed

MOT #13

2019-11-26 11:20

MOT test number

844725369729

Result

✓ Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #12** 2018-12-22 11:24**MOT test number** 223587857483**Result** Passed**MOT #11** 2018-12-21 10:30**MOT test number** 645406797152**Result** Failed

DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

DANGEROUS Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Service brake efficiency below requirements (1.2.2 (a) (i))

MAJOR Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

DANGEROUS Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

DANGEROUS Nearside Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #10 2017-12-28 09:42**MOT test number** 878511214915**Result** Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Rear Brake hose slightly deteriorated (3.6.B.4d)

MOT #9 2017-01-02 10:53**MOT test number** 660075176907**Result** Passed

Advice Nearside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #8** 2016-01-30 13:43**MOT test number** 418640406962**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2015-02-03 15:06**MOT test number** 195404235054**Result** ✓ Passed**MOT #6** 2015-02-02 12:10**MOT test number** 418593635068**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #5** 2014-01-25 11:30**MOT test number** 625175424033**Result** ✓ Passed**MOT #4** 2014-01-25 11:30**MOT test number** 826985224091**Result** ✗ Failed**Pass with rectification** Nearside Outer Front Front position lamp(s) not working (1.1.A.3b)



MOT #3	2012-11-24 11:04
MOT test number	819129322300
Result	✓ Passed
MOT #2	2011-11-23 12:03
MOT test number	429507321472
Result	✓ Passed
MOT #1	2010-12-17 14:21
MOT test number	464951450374
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
13 June 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	13 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	HN57LLX
Plate since	2019-09-28
Current registration	HN57LLX
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-12-10
Last registration	2023-06-14
Complete history	See info



Registration #1	2007-12-10	18 mi
Registration #2	2010-12-17	35.192 mi
Registration #3	2011-11-23	44.088 mi
Registration #4	2012-11-24	49.787 mi
Registration #5	2014-01-25	62.205 mi
Registration #6	2015-02-02	73.430 mi
Registration #7	2015-02-03	73.457 mi
Registration #8	2016-01-30	82.556 mi
Registration #9	2017-01-02	91.953 mi
Registration #10	2017-12-28	99.019 mi
Registration #11	2018-01-01	99.019 mi
Registration #12	2018-01-01	99.019 mi
Registration #13	2018-01-01	99.019 mi
Registration #14	2018-01-01	99.019 mi
Registration #15	2018-01-01	99.019 mi
Registration #16	2018-01-01	99.019 mi
Registration #17	2018-01-01	99.019 mi
Registration #18	2018-01-01	99.019 mi
Registration #19	2018-01-01	99.019 mi
Registration #20	2018-01-01	99.019 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1836 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1722 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	162344