



report date: 2024-03-28

General information

Make	FORD
Model	B-MAX ZETEC
Colour	White
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 104 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-10-14
Pictures	23
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-19
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	45
Total items failed	0

MOT #11	2023-09-28 16:52
MOT test number	456760990440
Result	✓ Passed
Next expiry date	2024-10-19
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10	2023-09-28 16:00
MOT test number	681506891598
Result	✗ Failed
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
DANGEROUS	Nearside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #9	2022-10-06 10:16
MOT test number	713010395908
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8** 2021-10-20 15:29**MOT test number** 672557969475**Result** ✓ Passed**MOT #7** 2021-09-08 13:45**MOT test number** 585137045286**Result** ✓ Passed**Advice** O/s/r tyre warn on inner and outer egdes**MOT #6** 2020-04-30 13:21**MOT test number** 509152306371**Result** ✓ Passed**Advice** Oil leak, but not excessive slight oil leak gearbox/engine area (8.4.1 (a) (i))**Advice** Offside Front mirror cover loose/been taped up**Minor** Nearside Front Windscreen wiper blade defective slight split middle of blade (3.4 (b) (i))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both discs (1.1.14 (a) (ii))**Advice** REAR WASHERS USED AS FRONT WASHERS**Advice** Rear Tyre worn close to legal limit/worn on edge both tyres 3mm (5.2.3 (e))

**MOT #5**

2020-04-28 14:20

MOT test number

660497040011

Result**✗ Failed**

- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both discs (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive slight oil leak gearbox/engine area (8.4.1 (a) (i))
- MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Offside Front Side repeater lens defective such that the emitted light is adversely affected tape over lens cant see from side (4.4.1 (b) (ii))
- Advice** Offside Front mirror cover loose/been taped up
- Minor** Nearside Front Windscreen wiper blade defective slight split middle of blade (3.4 (b) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge both tyres 3mm (5.2.3 (e))
- MAJOR** Front Windscreen washer not working (3.5 (a))

MOT #4

2019-03-28 09:39

MOT test number

111813766327

Result**✓ Passed**

- Advice** Nearside Rear unable to test seat belt (Child Seat)
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front wing mirror casing damaged and insecure not likely to fall
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #3** 2019-03-26 15:30**MOT test number** 172234635832**Result** ✗ Failed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Front wing mirror casing damaged and insecure not likely to fall**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear unable to test seat belt (Child Seat)**MOT #2** 2017-04-20 10:14**MOT test number** 268154385673**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2016-04-18 10:18**MOT test number** 942701675892**Result** ✓ Passed**Advice** Both front tyres bald on inner edges.



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
19 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-05-30
Last registration	2023-09-28
Complete history	See info



Registration #1	2013-05-30	9 mi
Registration #2	2016-04-18	27.147 mi
Registration #3	2017-04-20	31.283 mi
Registration #4	2019-03-26	40.513 mi
Registration #5	2019-03-28	40.513 mi
Registration #6	2020-04-28	44.343 mi
Registration #7	2020-04-30	44.384 mi
Registration #8	2020-05-20	45.277 mi
Registration #9	2020-05-20	45.277 mi
Registration #10	2020-05-20	45.277 mi
Registration #11	2020-05-20	45.277 mi
Registration #12	2020-05-20	45.277 mi
Registration #13	2020-05-20	45.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1208 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2

