



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA HDI DESIRE 2 PICASSO
Colour	Silver
Year of manufacture	-
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	205 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg



LABEL UNKNOWN



Internet history

Entry 3

Date	2022-01-19
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2

Date	2022-01-11
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-12-19
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #22	2021-12-09 12:15
MOT test number	530353801499
Result	✓ Passed
Next expiry date	2023-01-06
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #21	2021-01-07 14:43
MOT test number	313179756765
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2021-01-07 09:55
MOT test number	921959266782
Result	✗ Failed
MAJOR	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
MAJOR	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
MAJOR	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #19	2020-01-07 10:47
MOT test number	665407627106
Result	✓ Passed

**MOT #18** 2020-01-06 14:27**MOT test number** 677928308466**Result** ✗ Failed

- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Offside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17 2018-12-29 10:38**MOT test number** 941701915069**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16 2018-01-05 08:11**MOT test number** 248288438863**Result** ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Exhaust bracket broken

**MOT #15** 2017-12-28 16:03**MOT test number** 804387161646**Result** ✗ Failed**Fail** Rear Registration plate lamp not working (1.1.C.1d)**Advice** Exhaust bracket broken**Fail** Offside Outer Seat belt anchorage prescribed area is excessively corroded sill (5.2.6)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Outer Seat belt anchorage prescribed area is excessively corroded sill (5.2.6)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #14** 2016-10-29 14:39**MOT test number** 824035660923**Result** ✓ Passed**MOT #13** 2015-07-24 16:03**MOT test number** 569355805282**Result** ✓ Passed**MOT #12** 2014-06-27 09:47**MOT test number** 849328874197**Result** ✓ Passed**Notice** Both outter sills slightly corroded**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #11** 2014-06-27 09:47**MOT test number** 827198074190**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Notice** Both outter sills slightly corroded**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2013-06-28 09:31**MOT test number** 779459873195**Result** ✓ Passed**Notice** Both front tyres worn on edges and o/s/f tyre has cut on inner edge**MOT #9** 2013-06-28 09:31**MOT test number** 776579873137**Result** ✗ Failed**Notice** Both front tyres worn on edges and o/s/f tyre has cut on inner edge**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #8** 2012-06-30 09:47**MOT test number** 968572582192**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2012-06-29 09:46**MOT test number** 909441882173**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Rear Exhaust system not adequately supported (7.1.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2011-06-27 14:35**MOT test number** 298098271424**Result** ✓ Passed**MOT #5** 2010-06-22 15:23**MOT test number** 893943470139**Result** ✓ Passed**MOT #4** 2010-06-22 14:58**MOT test number** 371693370133**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Rear exhaust hanger



MOT #3	2009-06-30 09:44
MOT test number	883371989170
Result	✓ Passed
MOT #2	2008-07-03 12:53
MOT test number	202875788410
Result	✓ Passed
MOT #1	2008-01-14 09:15
MOT test number	122484018086
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-03-01
Last registration	2021-12-09
Complete history	See info



Registration #1	2005-03-01	11 mi
Registration #2	2008-01-14	27.475 mi
Registration #3	2008-07-03	32.267 mi
Registration #4	2009-06-30	42.868 mi
Registration #5	2010-06-22	54.562 mi
Registration #6	2010-06-22	54.562 mi
Registration #7	2011-06-27	64.562 mi
Registration #8	2012-06-29	73.952 mi
Registration #9	2012-06-30	73.952 mi
Registration #10	2013-06-28	83.213 mi
Registration #11	2014-06-27	92.903 mi
Registration #12	2015-07-24	102.696 mi
Registration #13	2016-06-29	112.488 mi
Registration #14	2017-06-29	122.280 mi
Registration #15	2018-06-29	132.072 mi
Registration #16	2019-06-29	141.864 mi
Registration #17	2020-06-29	151.656 mi
Registration #18	2021-06-29	161.448 mi
Registration #19	2022-06-29	171.240 mi
Registration #20	2023-06-29	181.032 mi
Registration #21	2024-06-29	190.824 mi
Registration #22	2025-06-29	200.616 mi
Registration #23	2026-06-29	210.408 mi
Registration #24	2027-06-29	220.200 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYTH4008339