



report date: 2024-03-29

General information

Make	FIAT
Model	500C LOUNGE
Colour	Grey
Year of manufacture	2015
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	111 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-09-14
Pictures	42
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-14
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	21
Total items failed	15

MOT #12	2023-10-12 10:41
MOT test number	947424626419
Result	✓ Passed
Next expiry date	2024-10-14
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front day time running lamp not working
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Suspension top mount worn

MOT #11	2023-10-11 12:50
MOT test number	590941893309
Result	✗ Failed
Advice	Nearside Front day time running lamp not working
Fail	Offside Rear Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Front Tyre has ply or cords exposed 195/45/16 (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Suspension top mount worn
Fail	Nearside Front Tyre has a lump, caused by separation or partial failure of its structure 195/45/16 (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10** 2022-10-13 15:41**MOT test number** 723130198301**Result** ✓ Passed**MOT #9** 2022-10-10 07:29**MOT test number** 367185628853**Result** ✗ Failed

- Fail** Offside Front Macpherson strut mounting damaged and seriously weakened (5.3.3 (b) (i))
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Macpherson strut mounting damaged and seriously weakened (5.3.3 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #8 2021-10-15 16:40**MOT test number** 754431137553**Result** ✓ Passed**MOT #7** 2021-02-15 16:44**MOT test number** 258831106440**Result** ✓ Passed

- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))



MOT #6

2021-02-15 08:58

MOT test number

738028890078

Result

✗ Failed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 27% (1.2.1 (b) (i))

Fail Nearside Front Tyre has ply or cords exposed 3/4 wear (5.2.3 (d) (ii))

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

Fail Offside Front Tyre tread depth below requirements of 1.6mm 3/4 wear (5.2.3 (e))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #5

2020-02-27 07:48

MOT test number

954689004571

Result

✓ Passed

MOT #4

2020-02-27 07:48

MOT test number

428774757975

Result

✗ Failed

Pass with rectification Offside Front Side repeater not working (4.4.1 (a) (ii))

MOT #3

2019-02-15 11:51

MOT test number

684023445422

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #2	2019-02-15 11:50
MOT test number	105779508697
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #1	2018-02-12 12:08
MOT test number	254465858188
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
14 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	14 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-01-30
Last registration	2023-10-12
Complete history	See info



Registration #1	2015-01-30	20 mi
Registration #2	2018-02-12	30.968 mi
Registration #3	2019-02-15	44.033 mi
Registration #4	2019-02-15	44.033 mi
Registration #5	2020-02-27	49.967 mi
Registration #6	2020-02-27	49.967 mi
Registration #7	2021-02-15	63.704 mi
Registration #8	2022-02-27	75.277 mi
Registration #9	2022-02-27	75.277 mi
Registration #10	2022-02-27	75.277 mi
Registration #11	2022-02-27	75.277 mi
Registration #12	2022-02-27	75.277 mi
Registration #13	2022-02-27	75.277 mi
Registration #14	2023-10-12	85.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats 4

Number of axles	2
Engine number	1197677