



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	Black
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-03
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #10	2021-07-13 09:33
MOT test number	747305970031
Result	✓ Passed
Next expiry date	2022-08-09
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #9	2020-08-10 09:14
MOT test number	875068954677
Result	✓ Passed
Advice	Lower Under tray fitted, full length of the car.
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #8	2019-07-02 11:09
MOT test number	614525381869
Result	✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #7	2018-07-18 10:49
MOT test number	283284012824
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

**MOT #6** 2017-06-06 12:15**MOT test number** 769495713005**Result** ✓ Passed**Advice** Front brake fluctuating, but not excessively o/s/f (3.7.B.3)**Advice** N/s/r and n/s/f tyre cracked on outer side wall**MOT #5** 2016-06-07 09:16**MOT test number** 628288388449**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #4** 2015-06-05 09:31**MOT test number** 267136055179**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2014-06-20 11:35**MOT test number** 425731574163**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #2	2013-07-03 08:37
MOT test number	529164183171
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #1	2013-05-13 12:49
MOT test number	329743233132
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components
Advice	Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AJ10YXX
Plate since	2019-03-29
Current registration	AJ10YXX
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-06-29
Last registration	2021-07-13
Complete history	See info



Registration #1	2010-06-29	7 mi
Registration #2	2013-05-13	27.036 mi
Registration #3	2013-07-03	27.678 mi
Registration #4	2014-06-20	32.987 mi
Registration #5	2015-06-05	41.020 mi
Registration #6	2016-06-07	49.283 mi
Registration #7	2016-06-07	55.277 mi
Registration #8	2016-06-07	55.277 mi
Registration #9	2016-06-07	55.277 mi
Registration #10	2016-06-07	55.277 mi
Registration #11	2016-06-07	55.277 mi
Registration #12	2016-06-07	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1361361