




report date: 2024-03-28

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Grey
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 3

Date	2021-09-02
Pictures	29
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 2

Date	2021-07-05
Pictures	25
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-03
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-01-20
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	24
Total items failed	8

MOT #13	2024-01-18 14:50
MOT test number	679359736539
Result	✓ Passed
Next expiry date	2025-01-20

MOT #12	2023-01-13 16:34
MOT test number	385589423342
Result	✓ Passed

MOT #11	2022-01-12 14:59
MOT test number	906839517044
Result	✓ Passed

MOT #10	2021-01-21 14:34
MOT test number	314639112156
Result	✓ Passed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2021-01-18 12:36**MOT test number** 555617371703**Result** ✗ Failed**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords also worn edge (5.2.3 (d) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords also worn edges 235/60/18 (5.2.3 (d) (i))**Advice** Nearside Rear Nail in tyre**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #8** 2019-12-19 17:30**MOT test number** 629667091158**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-01-10 09:20**MOT test number** 547695203106**Result** ✓ Passed**MOT #6** 2019-01-10 09:20**MOT test number** 758771412987**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #5** 2017-12-15 16:42**MOT test number** 423469068824**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit both worn on the inner edge (4.1.E.1)**Advice** Rear Radius arm has slight play in a pin/bush both (2.4.G.2)**Advice** Nearside Rear tyre perished/split**Advice** Offside Front Tyre worn close to the legal limit ON 1.6mm - badly worn on the inner edge (4.1.E.1)**MOT #4** 2017-12-15 16:42**MOT test number** 899913462605**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Rear Tyre worn close to the legal limit both worn on the inner edge (4.1.E.1)**Advice** Rear Radius arm has slight play in a pin/bush both (2.4.G.2)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear tyre perished/split**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit ON 1.6mm - badly worn on the inner edge (4.1.E.1)**MOT #3** 2017-01-13 17:02**MOT test number** 572127879985**Result** ✓ Passed



MOT #2	2015-11-28 11:29
MOT test number	632334224474
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside front tyre has a nail in tread.
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Both front tyres wearing unevenly on inner edges.

MOT #1	2015-11-28 10:15
MOT test number	877240158143
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Rear Stop lamp not working (1.2.1b)
Advice	Both front tyres wearing unevenly on inner edges.
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside front tyre has a nail in tread.



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
20 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	20 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-11-28
Last registration	2024-01-18
Complete history	<a href="#">See info</a>



Registration #1	2012-11-28	26 mi
Registration #2	2015-11-28	22.856 mi
Registration #3	2015-11-28	22.856 mi
Registration #4	2017-01-13	39.756 mi
Registration #5	2017-12-15	54.505 mi
Registration #6	2017-12-15	54.505 mi
Registration #7	2019-01-10	70.812 mi
Registration #8	2019-01-10	70.812 mi
Registration #9	2019-12-19	85.075 mi
Registration #10	2020-01-20	95.377 mi
Registration #11	2020-01-20	95.377 mi
Registration #12	2020-01-20	95.377 mi
Registration #13	2020-01-20	95.377 mi
Registration #14	2020-01-20	95.377 mi
Registration #15	2020-01-20	95.377 mi
Registration #16	2020-01-20	95.377 mi
Registration #17	2020-01-20	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	202373K