



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 ALLURE COUPE CABRIOLET
Colour	Blue
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	190 Nm at 4.100 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	45.6 mpg
Consumption combined	35.3 mpg





Internet history

Entry 1

Date	2021-09-23
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



## MOT history

MOT #24	2022-06-08 15:22
MOT test number	719352469985
Result	✓ Passed
Next expiry date	2023-06-15
Advice	Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))
Advice	Power steering pipe/hose has slight seepage (2.1.5 (a))
Advice	Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c))
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #23	2022-06-08 08:01
MOT test number	549849412123
Result	✗ Failed
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))
Advice	Power steering pipe/hose has slight seepage (2.1.5 (a))
Advice	Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c))

MOT #22	2021-06-16 08:25
MOT test number	400246828842
Result	✓ Passed
Advice	Front Coil spring corroded Both (5.3.1 (b) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #21**

2021-06-11 10:04

**MOT test number**

518372998895

**Result****✗ Failed**

- Fail** Rear Exhaust has a major leak of exhaust gases Exhaust box (6.1.2 (a))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Coil spring corroded Both (5.3.1 (b) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #20**

2020-01-25 11:06

**MOT test number**

879668463696

**Result****✓ Passed**

- Advice** Front Coil spring corroded both (5.3.1 (b) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #19** 2020-01-25 08:48**MOT test number** 893511868467**Result** ✗ Failed

- Fail** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))
- Fail** Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Horn not working (7.7 (a) (ii))
- Advice** Front Coil spring corroded both (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #18** 2020-01-11 10:36**MOT test number** 621395916532**Result** ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Coil spring corroded both (5.3.1 (b) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

**MOT #17** 2018-12-21 14:37**MOT test number** 802795890750**Result** ✓ Passed

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #16** 2018-12-21 09:48**MOT test number** 952832850989**Result** ✗ Failed**Fail** Side repeater incorrect colour both (4.4.3 (a))**Fail** Exhaust system insecure (6.1.2 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #15** 2017-12-15 12:08**MOT test number** 215379198698**Result** ✓ Passed**MOT #14** 2017-12-01 10:59**MOT test number** 896266633953**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Rear fog lamp not working (1.3.2b)**MOT #13** 2016-12-07 12:10**MOT test number** 788697581360**Result** ✓ Passed**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #12** 2016-12-02 11:16**MOT test number** 575811326639**Result** ✗ Failed

**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #11** 2015-12-11 10:24**MOT test number** 655856494989**Result** ✓ Passed**MOT #10** 2014-12-06 10:09**MOT test number** 759880944390**Result** ✓ Passed

**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #9** 2013-12-03 12:22**MOT test number** 255677333379**Result** ✓ Passed

**Notice** Offside wiper blade starting to split

**Notice** Offside handbrake low

**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #8** 2012-12-10 11:13**MOT test number** 427395542304**Result** ✓ Passed

**MOT #7** 2012-12-10 11:13**MOT test number** 577605742391**Result** ✗ Failed**Pass with rectification** Nearside Rear Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2011-12-13 11:06**MOT test number** 508067841382**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2010-12-14 11:02**MOT test number** 101518840303**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2009-12-09 10:11**MOT test number** 770293649366**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)

**MOT #3** 2008-11-14 10:40**MOT test number** 293009118360**Result** ✓ Passed**MOT #2** 2007-11-17 09:24**MOT test number** 363731827385**Result** ✓ Passed**MOT #1** 2007-03-09 10:49**MOT test number** 304398367052**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>AK04XOR</b>
Plate since	2024-03-28
Current registration	<b>AK04XOR</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-03-31
Last registration	2022-06-08
Complete history	<a href="#">See info</a>



Registration #1	2004-03-31	15 mi
Registration #2	2007-03-09	17.450 mi
Registration #3	2007-11-17	20.743 mi
Registration #4	2008-11-14	31.234 mi
Registration #5	2009-12-09	42.226 mi
Registration #6	2010-12-14	46.030 mi
Registration #7	2011-12-13	52.322 mi
Registration #8	2012-12-10	58.778 mi
Registration #9	2013-12-03	62.102 mi
Registration #10	2014-12-06	65.459 mi
Registration #11	2015-12-11	68.665 mi
Registration #12	2016-12-02	72.834 mi
Registration #13	2016-12-07	72.834 mi
Registration #14	2016-12-07	72.834 mi
Registration #15	2016-12-07	72.834 mi
Registration #16	2016-12-07	72.834 mi
Registration #17	2016-12-07	72.834 mi
Registration #18	2016-12-07	72.834 mi
Registration #19	2016-12-07	72.834 mi
Registration #20	2016-12-07	72.834 mi
Registration #21	2016-12-07	72.834 mi
Registration #22	2016-12-07	72.834 mi
Registration #23	2016-12-07	72.834 mi
Registration #24	2016-12-07	72.834 mi
Registration #25	2016-12-07	72.834 mi



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1673 mm
Height	1373 mm
Length	3835 mm
Wheel base	2442 mm
Kerb weight	1152 kg
Max. allowed weight	1562 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	LH1Z1106488