



report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Blue
Year of manufacture	2010
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-12-02
Pictures	6
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-03-09
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	33
Total items failed	11

MOT #172023-02-27 16:14

MOT test number873047107366

Result✓ Passed

Next expiry date2024-03-09

- AdviceOffside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceNearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceNearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceOffside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceOffside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceNearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16**

2023-02-27 11:24

MOT test number

458097154500

Result**✗ Failed****Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Service brake has no recorded effort at a wheel (1.2.1 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2022-03-10 10:16

MOT test number

271355371428

Result**✓ Passed****MOT #14**

2021-08-05 14:32

MOT test number

594135891283

Result**✓ Passed****MOT #13**

2021-08-05 09:56

MOT test number

426430536726

Result**✗ Failed****Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

**MOT #12**

2020-11-30 10:08

MOT test number

380976934584

Result

✓ Passed

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))**Advice** Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))**Advice** Fuel Pipe/s corroded**Advice** Both front inner c.v boot seeping grease**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11**

2019-06-07 16:30

MOT test number

365906570155

Result

✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material main pipe to rear flexible hose (1.1.11 (c))**MOT #10**

2019-06-07 12:58

MOT test number

784560551364

Result

✗ Failed

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material main pipe to rear flexible hose (1.1.11 (c))**MOT #9**

2018-05-09 09:10

MOT test number

997723929696

Result

✓ Passed

**MOT #8** 2017-08-23 15:21**MOT test number** 901967105545**Result** ✓ Passed

Advice Offside Suspension arm rubber bush deteriorated but not resulting in excessive movement and nearside front (rear bush) (2.4.G.2)

Advice Nearside Brake pipe slightly corroded main (3.6.B.2c)

MOT #7 2017-08-22 12:47**MOT test number** 551524743114**Result** ✗ Failed

Fail Nearside Headlamp not working on dipped beam (1.7.5a)

Advice Nearside Brake pipe slightly corroded main (3.6.B.2c)

Fail Offside Brake pipe excessively corroded main (3.6.B.2c)

Advice Offside Suspension arm rubber bush deteriorated but not resulting in excessive movement and nearside front (rear bush) (2.4.G.2)

MOT #6 2016-09-01 15:49**MOT test number** 489301916012**Result** ✓ Passed

Advice N/S/R HAS A VERY DEEP CUT ON TREAD WITH NO CORDS SHOWING YET

Advice O/S/R TYRE HAS A CRACKING ON TREAD WITH NO CORDS SHOWING

MOT #5 2016-02-02 10:43**MOT test number** 102972630246**Result** ✓ Passed**MOT #4** 2015-03-11 12:11**MOT test number** 119560175445**Result** ✓ Passed



MOT #3 2015-03-05 16:25

MOT test number 647504765015

Result ✗ Failed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Headlamp aim too low (1.8)

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Front brake excessively fluctuating (3.7.B.3)

Notice Nsf tyre has deep cut in sidewall

Fail Offside front brake binding (3.7.B.1)

MOT #2 2014-05-15 11:45

MOT test number 708205134103

Result ✓ Passed

MOT #1 2013-06-12 09:16

MOT test number 525273563152

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✗
MOT

Expired:
9 March 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	9 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-10-28
Last registration	2023-02-27
Complete history	See info



Registration #1	2010-10-28	24 mi
Registration #2	2013-06-12	9.372 mi
Registration #3	2014-05-15	12.378 mi
Registration #4	2015-03-05	17.912 mi
Registration #5	2015-03-11	17.914 mi
Registration #6	2016-02-02	21.414 mi
Registration #7	2016-09-01	23.955 mi
Registration #8	2017-08-22	32.428 mi
Registration #9	2017-08-23	32.428 mi
Registration #10	2018-05-09	38.414 mi
Registration #11	2019-05-29	39.377 mi
Registration #12	2019-05-29	39.377 mi
Registration #13	2019-05-29	39.377 mi
Registration #14	2019-05-29	39.377 mi
Registration #15	2019-05-29	39.377 mi
Registration #16	2019-05-29	39.377 mi
Registration #17	2019-05-29	39.377 mi
Registration #18	2019-05-29	39.377 mi
Registration #19	2019-05-29	39.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	124256