



E009CSU

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO BLUEMOTION 2 TDI (80BHP)
Colour	Silver
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	195 Nm at 1.800 rpm
Cylinders	3
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	83.1 mpg
Consumption combined	68.9 mpg





MOT history

MOT #16	2022-10-17 13:36
MOT test number	680591451515
Result	✓ Passed
Next expiry date	2023-10-21
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #15	2021-10-22 08:51
MOT test number	838716995097
Result	✓ Passed
Minor	Windscreen excessively tinted but not adversely affecting driver's view (3.2 (b) (i))
Minor	Offside Front Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))
Minor	Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))
Minor	Nearside Front Window excessively tinted but not adversely affecting driver's view (3.2 (b) (i))

MOT #14	2020-10-13 12:46
MOT test number	608441662214
Result	✓ Passed

MOT #13	2020-10-12 07:47
MOT test number	978902487220
Result	✗ Failed
Fail	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #12	2019-07-11 10:19
MOT test number	957690038995
Result	✓ Passed

**MOT #11** 2019-07-10 10:27**MOT test number** 361428034805**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #10** 2018-08-22 10:38**MOT test number** 377138781687**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2018-08-22 10:38**MOT test number** 392549287597**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #8** 2017-08-30 09:16**MOT test number** 962193995656**Result** ✓ Passed

**MOT #7** 2017-08-30 09:16**MOT test number** 249014974871**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Pass with rectification** Offside Front Headlamp aim too low (1.8)**MOT #6** 2017-08-29 16:20**MOT test number** 763601405327**Result** ✗ Failed**Fail** Nearside Front Headlamp insecure (1.7.3)**Fail** Offside Front Headlamp aim too high (1.8)**Advice** Engine Light On**Advice** Items removed from driver's view prior to test**Fail** Offside Front Headlamp insecure (1.7.3)**Advice** Vehicle has covers fitted unable to see certain testable items**Fail** Nearside Front Headlamp aim too low (1.8)**Advice** Exhaust System is Corroded**MOT #5** 2016-07-16 10:41**MOT test number** 986468003305**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2015-02-24 11:08**MOT test number** 908865355043**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-03-01 12:07**MOT test number** 266100164062**Result** ✓ Passed**Notice** Oil leak from rear of engine**MOT #2** 2013-02-22 10:39**MOT test number** 426243553028**Result** ✓ Passed**MOT #1** 2012-02-20 15:01**MOT test number** 368601152020**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-04
Last registration	2022-10-17
Complete history	See info



Registration #1	2009-03-04	22 mi
Registration #2	2012-02-20	18.796 mi
Registration #3	2013-02-22	22.407 mi
Registration #4	2014-03-01	25.597 mi
Registration #5	2015-02-24	27.721 mi
Registration #6	2016-07-16	27.828 mi
Registration #7	2017-08-29	31.005 mi
Registration #8	2017-08-30	31.011 mi
Registration #9	2017-08-30	31.011 mi
Registration #10	2019-05-29	35.377 mi
Registration #11	2019-05-29	35.377 mi
Registration #12	2019-05-29	35.377 mi
Registration #13	2019-05-29	35.377 mi
Registration #14	2019-05-29	35.377 mi
Registration #15	2019-05-29	35.377 mi
Registration #16	2019-05-29	35.377 mi
Registration #17	2019-05-29	35.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1267 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BMS045170