



report date: 2024-03-28

General information

| | |
|---------------------|-----------------------------|
| Make | CITROEN |
| Model | C4 GRAND PURETECH FLAIR S/S |
| Colour | Black |
| Year of manufacture | 2019 |
| Top speed | 124 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 128 BHP |
| Max. torque | 230 Nm at 1.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 45.6 mpg |
| CO2 emission | 118 g/km |
| CO2 label | C |





Internet history

Entry 3


| | |
|---------------|-----------------------------|
| Date | 2022-03-03 |
| Pictures | 10 |
| Listing price | View report |



source: autoonline.co.uk

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-02-27 |
| Pictures | 11 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-02-26 |
| Pictures | 11 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-10 |
| MOT pass rate | 50 % |
| MOT passed | 3 |
| Failed MOT tests | 3 |
| Total advice items | 28 |
| Total items failed | 6 |

| | |
|------------------|--|
| MOT #6 | 2024-01-29 14:04 |
| MOT test number | 162205498964 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-10 |
| Advice | Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)) |
| Advice | Central Rear Child Seat fitted not allowing full inspection of adult belt |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt |

| | |
|-----------------|--|
| MOT #5 | 2024-01-29 10:16 |
| MOT test number | 395103327632 |
| Result | ✗ Failed |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt |
| Fail | Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Advice | Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)) |
| Advice | Central Rear Child Seat fitted not allowing full inspection of adult belt |
| Fail | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt |

**MOT #4**

2023-02-02 11:48

MOT test number

997867536840

Result

✓ Passed

- Advice** Front Inner brake discs friction surface corroded and in a poor condition
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Child Seat fitted not allowing full inspection of adult belt Middle Row
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Child Seat fitted not allowing full inspection of adult belt Middle Row

MOT #3

2023-02-02 11:48

MOT test number

881425925011

Result

✗ Failed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Child Seat fitted not allowing full inspection of adult belt Middle Row
- Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Inner brake discs friction surface corroded and in a poor condition
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Child Seat fitted not allowing full inspection of adult belt Middle Row
- Pass with rectification** Windscreen washer not working (3.5 (a))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #2** 2022-01-14 14:33**MOT test number** 311413568059**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #1** 2021-12-16 14:27**MOT test number** 331117184955**Result** ✗ Failed**Fail** Nearside Front Headlamp insecure (4.1.1 (c))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Front Headlamp aim too low (4.1.2 (a))



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
10 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 10 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |




Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |   |
| Plate since | 2024-03-28 |
| Current registration |   |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2019-02-11 |
| Last registration | 2024-01-29 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2019-02-11 | 22 mi |
| Registration #2 | 2021-12-16 | 33.630 mi |
| Registration #3 | 2022-01-14 | 33.632 mi |
| Registration #4 | 2022-01-14 | 33.632 mi |
| Registration #5 | 2022-01-14 | 33.632 mi |
| Registration #6 | 2022-01-14 | 33.632 mi |
| Registration #7 | 2022-01-14 | 33.632 mi |
| Registration #8 | 2022-01-14 | 33.632 mi |
| Registration #9 | 2022-01-14 | 33.632 mi |
| Registration #10 | 2022-01-14 | 33.632 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 85% |
| Pedestrian | 43% |
| Safety systems | 97% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1826 mm |
| Height | 1644 mm |
| Length | 4602 mm |
| Wheel base | 2840 mm |
| Kerb weight | 1320 kg |
| Max. allowed weight | 2095 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Number of axles | 2 |
| Engine number | XVAW1304649 |