



report date: 2024-03-29

General information

Make	BMW
Model	X5 D M SPORT
Colour	Grey
Year of manufacture	2009
Top speed	130 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	235 BHP
Max. torque	520 Nm at 2.000 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.0 mpg
Consumption extra urban	39.2 mpg
Consumption combined	32.5 mpg
CO2 emission	214 g/km
CO2 label	K







Internet history

Entry 1

Date	2021-06-13
Pictures	42
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-06-16
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	14
Total items failed	5

MOT #12	2021-06-17 09:07
MOT test number	857143025843
Result	✓ Passed
Next expiry date	2022-06-16

MOT #11	2021-06-14 14:23
MOT test number	514682546641
Result	✗ Failed

- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Suspension arm pin or bush worn but not resulting in excessive movement all sides (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2019-09-05 09:22**MOT test number** 932370716972**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front arm bush (5.3.4 (a) (i))**Advice** Offside Front brake disc slightly lipped and worn**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Under covers fitted**Advice** Offside Front Lower Suspension arm ball joint has slight play rear arm (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front arm bush (5.3.4 (a) (i))**Advice** Offside Rear tyre wearing inner edge badly but no ply or cords found**Advice** Nearside Front Lower Suspension arm ball joint has slight play rear arm (5.3.4 (a) (i))**MOT #9** 2018-06-07 14:09**MOT test number** 589806580605**Result** ✓ Passed**MOT #8** 2018-06-07 08:35**MOT test number** 562727760930**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #7** 2017-06-12 10:47**MOT test number** 520565004777**Result** ✓ Passed**MOT #6** 2016-06-13 15:01**MOT test number** 142821838496**Result** ✓ Passed

**MOT #5** 2015-04-07 09:33**MOT test number** 158597095027**Result** ✓ Passed**MOT #4** 2014-03-24 11:06**MOT test number** 136343684037**Result** ✓ Passed**MOT #3** 2013-03-19 13:56**MOT test number** 106978873063**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-03-16 16:08**MOT test number** 755916672093**Result** ✓ Passed**MOT #1** 2012-03-13 11:03**MOT test number** 959473172070**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-03-24
Last registration	2021-06-17
Complete history	See info



Registration #1	2009-03-24	25 mi
Registration #2	2012-03-13	30.894 mi
Registration #3	2012-03-16	30.899 mi
Registration #4	2013-03-19	41.933 mi
Registration #5	2014-03-24	47.977 mi
Registration #6	2015-04-07	58.782 mi
Registration #7	2016-06-13	71.041 mi
Registration #8	2017-06-20	85.277 mi
Registration #9	2018-06-20	95.277 mi
Registration #10	2019-06-20	105.277 mi
Registration #11	2020-06-20	115.277 mi
Registration #12	2021-06-17	125.277 mi
Registration #13	2022-06-20	135.277 mi
Registration #14	2023-06-20	145.277 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1994 mm
Height	1764 mm
Length	4851 mm
Wheel base	2933 mm
Max. allowed weight	2755 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	21716857