





report date: 2024-03-29

#### General information

Make	AUDI
Model	A3 TDI SPORT
Colour	Silver
Year of manufacture	2007
Top speed	128 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	188 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	143 g/km
CO2 label	F



CarCheck.co.uk page 1/13



# MOT history

MOT expiry date	2021-11-24
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	38
Total items failed	6

MOT #17		2020-11-25 14:39
MOT test	number	824464917171
Result		✓ Passed
Next expi	ry date	2021-11-24
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/13



Minor

YY57JOA report date: 2024-03-29

**MOT #16** 2020-11-19 13:04 **MOT** test number 202497343435 Result × Failed **MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Advice **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #15

MOT test number

Result

Advice

Offside Rear Tyre worn close to legal limit/worn on edge Under inflated, (5.2.3 (e))

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

 MOT #14
 2018-06-19 11:27

 MOT test number
 811166258808

 Result
 ✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

Passed

**MOT #13** 2017-07-04 17:21

**MOT** test number 322089440488

Result Passed

**Advice** 

Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt

(2.5.C.1a)

Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt

Advice (2.5.C.1a)

**MOT #12** 2017-07-03 10:29

**MOT** test number 254246781773

Result × Failed

**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #11** 2016-07-06 10:43

**MOT** test number 800346933059

Result ✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit Nail in tread. (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit edgy inside and out. (4.1.E.1)

Advice Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt

(2.5.C.1a)

**MOT #10** 2015-06-29 13:55

457460685175 **MOT test number** 

Result

**Notice** Engine oil on min.

CarCheck.co.uk page 4/13



MOT #9 2015-06-29 13:00

**MOT test number** 569830885109

Result X Failed

**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Notice** Engine oil on min.

MOT #8 2014-06-26 12:22

MOT test number 969287274143

Result \( \sqrt{Passed} \)

**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #7 2014-06-26 12:22

MOT test number 628747874157

**Result** X Failed

**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Pass with rectification** Offside Stop lamp not working (1.2.1b)

MOT #6 2013-06-26 15:39

MOT test number 338607873175

**Result** 
✓ Passed

**Notice** Front wipers smearing, but clearing effectively

**Notice** Engine covers fitted obscuring some components in the engine bay

**Notice** Minor split in o/s/f cv boot

CarCheck.co.uk page 5/13



MOT #5 2013-06-26 12:20

MOT test number 727027773134

**Result** X Failed

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**Notice** Minor split in o/s/f cv boot

Fail Offside Rear Headlamp aim beam image obviously incorrect (1.8.A.1b)

**Notice** Front wipers smearing, but clearing effectively

**Notice** Engine covers fitted obscuring some components in the engine bay

MOT #4 2012-06-27 11:06

**MOT test number** 307069672136

**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #3 2011-06-29 12:09

**MOT test number** 218580881490

Result \( \sqrt{Passed} \)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2011-06-29 12:09

MOT test number 205340381406

**Result** X Failed

**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 6/13



MOT #1 2010-11-02 09:42 MOT test number 963716100313

**Result** ✓ Passed

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



### Owner history

e when miscery	
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-12-13
Last registration	2020-11-25
Complete history	See info



Registration #1	2007-12-13	12 mi
Registration #2	2010-11-02	54.432 mi
Registration #3	2011-06-29	67.527 mi
Registration #4	2012-06-27	77.446 mi
Registration #5	2013-06-26	87.941 mi
Registration #6	2013-06-26	87.941 mi
Registration #7	2014-06-26	97.532 mi
Registration #8	2015-06-29	105.798 mi
Registration #9		71.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		71.777 es
Registration #13		11.177 es
Registration #14		11.777 es
Registration #15		
registration # 25		

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4286 mm
Wheel base	2578 mm
Kerb weight	1380 kg
Max. allowed weight	1930 kg

## Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

**Engine number** BKD B93032