



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC 16V
Colour	Blue
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	170 Nm at 4.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.2 mpg
CO2 emission	182 g/km
CO2 label	I







Internet history

Entry 1

Date	2021-05-21
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-27
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	26
Total items failed	9

MOT #20	2023-07-17 09:16
MOT test number	352815095192
Result	✓ Passed
Next expiry date	2024-07-27

MOT #19	2022-07-28 15:45
MOT test number	607180800343
Result	✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	O/S/R lens damaged and repaired with tape, not showing white light at time of test

**MOT #18**

2022-06-27 15:39

MOT test number

757882120314

Result**✗ Failed**

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Hydraulic brake calliper leaking At handbrake fulcrum (1.1.16 (b) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Rear Position lamp showing white light to the rear Damaged / incomplete (4.2.3 (a) (ii))
- Fail** Nearside Front Tyre has ply or cords exposed Inner shoulder (5.2.3 (d) (ii))

MOT #17

2021-06-22 10:30

MOT test number

482093235925

Result**✓ Passed**

- Advice** Handbrake travel but not excessive
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Unable to inspect front and rear pads
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2021-06-22 08:39

MOT test number

148586471886

Result**✗ Failed**

- Advice** Handbrake travel but not excessive
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Unable to inspect front and rear pads
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #15

2020-11-17 15:46

MOT test number

108882416396

Result**✓ Passed**

- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #14

2019-05-14 08:07

MOT test number

509116714152

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

2019-05-13 12:34

MOT test number

320362820062

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))



MOT #12	2018-05-09 09:11
----------------	------------------

MOT test number	279497650816
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #11	2017-05-16 13:14
----------------	------------------

MOT test number	803084516607
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

MOT #10	2016-05-16 08:21
----------------	------------------

MOT test number	724158328736
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2015-05-05 12:32
---------------	------------------

MOT test number	278145425404
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2014-05-07 12:35
---------------	------------------

MOT test number	729967524104
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2013-05-07 12:38
---------------	------------------

MOT test number	647657323128
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2012-05-14 12:47
---------------	------------------

MOT test number	308665332145
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #5** 2011-05-17 15:11**MOT test number** 507167531180**Result** ✓ Passed**MOT #4** 2010-04-28 12:34**MOT test number** 121538410133**Result** ✓ Passed**MOT #3** 2009-04-24 10:30**MOT test number** 621194219100**Result** ✓ Passed**Notice** N/S/R tyre has deep cut to tread.**Advice** Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** O/S/F tyre has bald inner edge.**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**MOT #2** 2009-04-24 10:01**MOT test number** 810934819142**Result** ✗ Failed**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Notice** N/S/R tyre has deep cut to tread.**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**Notice** O/S/F tyre has bald inner edge.**Advice** Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #1** 2008-04-23 12:29**MOT test number** 894904718172**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
27 July 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EJ05AAK
Plate since	2019-03-29
Current registration	EJ05AAK
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-04-27
Last registration	2023-07-17
Complete history	See info



Registration #1	2005-04-27	15 mi
Registration #2	2008-04-23	10.579 mi
Registration #3	2009-04-24	14.782 mi
Registration #4	2009-04-24	14.782 mi
Registration #5	2010-04-28	14.981 mi
Registration #6	2011-05-17	15.314 mi
Registration #7	2012-05-14	15.415 mi
Registration #8	2013-05-07	15.528 mi
Registration #9	2014-05-07	15.593 mi
Registration #10	2015-05-05	15.606 mi
Registration #11	2016-05-16	24.694 mi
Registration #12	2016-05-16	25.277 mi
Registration #13	2016-05-16	25.277 mi
Registration #14	2016-05-16	25.277 mi
Registration #15	2016-05-16	25.277 mi
Registration #16	2016-05-16	25.277 mi
Registration #17	2016-05-16	25.277 mi
Registration #18	2016-05-16	25.277 mi
Registration #19	2016-05-16	25.277 mi
Registration #20	2016-05-16	25.277 mi
Registration #21	2016-05-16	25.277 mi
Registration #22	2016-05-16	25.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1931 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Kerb weight	1388 kg
Max. allowed weight	1910 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	5B10461
---------------	---------