





report date: 2024-03-29

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Black
Year of manufacture	2014
Top speed	109 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 kW / 101 HP / 99 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29


Internet history

Entry 1

Date 2021-01-22

Pictures 13

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$	
N/I	α	history
_ IVI	C) I	THISCULV
		,

MOT expiry date	2024-09-17
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	13
Total items failed	6

MOT #12	2023-09-18 08:56
MOT test number	713256452245
Result	✓ Passed
Next expiry date	2024-09-17

MOT #11		2023-09-18 08:56
MOT test number		814679352832
Result		× Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #10	2023-05-03 15:37
MOT test number	106115243975
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9 2023-05-03 09:18

MOT test number 775044755334

Result X Failed

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2022-05-11 16:29

MOT test number 554937092158

Result

Passed

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #7 2022-05-11 09:55

MOT test number 227257180532

Result × Failed

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #6 2021-05-18 08:37

MOT test number 324778200285

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5	2021-05-13 15:48
MOT test number	590917370072
Result	× Failed
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification Windscreen washer not working (3.5 (a))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2019-10-29 10:58
MOT test number	927887549155
Result	✓ Passed
Advice Play in steering rack inner joint(s)	

MOT #3	2018-10-26 11:31
MOT test number	170661294367
Result	✓ Passed
MOT #2	2018-06-26 10:12
MOT test number	474958797750
Result	✓ Passed
Advice Rear both rear tyres cracked and perished but no ply or cords exposed	

MOT #1	2017-06-27 12:58
MOT test number	403243281362
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Expires: 17 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	17 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

IWO		la i a t	
U JAAV I	101	misi	$\mathbf{O} \mathbf{I} \mathbf{V}$

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK AR
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-06-30
Last registration	2023-09-18
Complete history	See info



Registration #1	2014-06-30	26 mi
Registration #2	2017-06-27	22.797 mi
Registration #3	2018-06-26	28.765 mi
Registration #4	2018-10-26	30.052 mi
Registration #5	2019-10-29	37.932 mi
Registration #6		71.777 es
Registration #7	2021-05-13	44.623 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	48 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	e 12/12

Number of axles2Engine numberES23713