



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 1700 CDTI
Colour	Red
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2025-04-01
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	15
Total items failed	13

MOT #15	2024-04-02 10:49
MOT test number	564713972866
Result	✓ Passed
Next expiry date	2025-04-01
Advice	Offside Front Play in steering rack inner joint(s)
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))
Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14**

2024-03-21 15:39

MOT test number

963956379553

Result**✗ Failed****Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))**Advice** Offside Front Play in steering rack inner joint(s)**Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Side repeater incorrect colour (4.4.3 (a))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #13**

2023-03-15 16:58

MOT test number

540836019363

Result**✓ Passed**

**MOT #12** 2022-03-26 10:18**MOT test number** 238916780576**Result** ✓ Passed

Advice Brake pipe corroded, covered in grease or other material all brake pipes covered not allowing full inspection (1.1.11 (c))

Minor Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction wipers no stopping in correct place (3.1 (a) (i))

MOT #11 2022-03-24 14:44**MOT test number** 401899454141**Result** ✗ Failed

Fail Nearside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

Minor Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction wipers no stopping in correct place (3.1 (a) (i))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt cv joint (6.1.7 (g) (ii))

Fail Front Windscreen in an unacceptable condition (3.2 (c) (i))

Advice Brake pipe corroded, covered in grease or other material all brake pipes covered not allowing full inspection (1.1.11 (c))

MOT #10 2021-03-18 11:41**MOT test number** 569143258788**Result** ✓ Passed**MOT #9** 2020-05-19 16:07**MOT test number** 472471318706**Result** ✓ Passed**MOT #8** 2019-05-21 07:03**MOT test number** 694278568823**Result** ✓ Passed



MOT #7	2018-06-12 14:28
MOT test number	702681202150
Result	✓ Passed
MOT #6	2017-06-20 06:09
MOT test number	724168568188
Result	✓ Passed
MOT #5	2016-06-20 13:44
MOT test number	811100766169
Result	✓ Passed
MOT #4	2015-06-18 09:17
MOT test number	977929065112
Result	✓ Passed
MOT #3	2014-06-24 07:17
MOT test number	445415974164
Result	✓ Passed
MOT #2	2013-06-22 10:43
MOT test number	509353773174
Result	✓ Passed
<div>Notice Oil leak on nearside driveshaft</div>	
MOT #1	2012-09-17 15:09
MOT test number	755091062272
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
1 April 2025

Tax status	Valid until 1 November
-------------------	------------------------

Days left	186
------------------	-----

MOT expiry date	1 April 2025
------------------------	--------------

Full MOT history	See MOT history
-------------------------	---------------------------------




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner 1	2015-01-01
Owner 2	2015-01-01
Owner 3	2015-01-01
Owner 4	2015-01-01
Owner 5	2015-01-01
Owner 6	2015-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 WR10BHD
Plate since	2015-01-01
Current registration	 WR10BHD
Plate since	2015-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-30
Last registration	2024-04-02
Complete history	See info



Registration #1	2010-03-30	9 mi
Registration #2	2012-09-17	9.889 mi
Registration #3	2013-06-22	13.426 mi
Registration #4	2014-06-24	18.214 mi
Registration #5	2015-06-18	22.615 mi
Registration #6	2016-06-20	27.520 mi
Registration #7	2017-06-20	32.177 mi
Registration #8	2018-06-12	36.875 mi
Registration #9	2019-06-20	41.573 mi
Registration #10	2020-06-20	46.271 mi
Registration #11	2021-06-20	50.969 mi
Registration #12	2022-06-20	55.667 mi
Registration #13	2023-06-20	60.365 mi
Registration #14	2024-03-29	65.063 mi
Registration #15	2024-03-29	65.063 mi
Registration #16	2024-03-29	65.063 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1210 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	3674463