





report date: 2024-03-29

General information

Make	KIA
Model	CARENS 2 ECODYNAMICS CRDI
Colour	Blue
Year of manufacture	2015
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry	1

Life y 1	
Date	2021-02-11
Pictures	0
Listing price	View report

source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-16
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	25
Total items failed	1

MOT #9		2024-04-09 11:39
MOT test	number	203327454798
Result		✓ Passed
Next expiry date 2025-04		2025-04-16
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8		2023-04-17 07:34
MOT test	number	593137195603
Result		✓ Passed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice	Nearside washer jet weak	

CarCheck.co.uk page 3/12



MOT #7 2022-02-04 12:34

MOT test number 851727337063

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Parking brake efficiency only just met. It would appear that the braking system requires

adjustment or repair. (1.4.2 (a) (i))

MOT #6 2020-12-23 11:04

MOT test number 269718888605

Result \(\sqrt{Passed} \)

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

MOT #5 2020-12-23 11:04

MOT test number 410703153222

Result × Failed

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #4 2019-06-24 09:56

MOT test number 642809354526

Result
✓ Passed

MOT #3 2019-06-22 09:45

MOT test number 307199141571

Result ★ Failed

DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



MOT #2	2018-06-30 10:5
MOT test	number 35793378136
Result	✓ Passe
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Tyre worn close to legal limit/worn on edge 1.6mm and outer edge is bold (5.2.3 (e))
Advice (e))	Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm and outer edge is bold (5.2.3

MOT #1		2018-06-30 10:11
MOT test	number	749860485856
Result		🗙 Failed
DANGER	OUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice (e))	Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm and oute	er edge is bold (5.2.3
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 1.6mm and outer	edge is bold (5.2.3 (e))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier meeory	
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	
manus .	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-18
Last registration	2024-04-09
Complete history	See info



Registration #1	2015-06-18	28 mi
Registration #2	2018-06-30	25.669 mi
Registration #3	2018-06-30	25.669 mi
Registration #4	2019-06-22	33.255 mi
Registration #5	2019-06-24	33.258 mi
Registration #6	2020-12-23	46.095 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 ms
Registration #10		11.777 es
Registration #11		10.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	76%
Pedestrian	64%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1805 mm
Height	1605 mm
Length	4525 mm
Wheel base	2750 mm
Kerb weight	1706 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2

Engine number D4FDEU497501