



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Silver
Year of manufacture	2004
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	130 Nm at 4.400 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-07
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-01
MOT pass rate	90 %
MOT passed	18
Failed MOT tests	2
Total advice items	46
Total items failed	8

MOT #20	2024-01-16 16:22
---------	------------------

MOT test number	964818016199
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-01
------------------	------------

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive all (5.3.6 (a) (i))
- Advice** Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #19**

2024-01-16 15:02

MOT test number

497902327856

Result**✗ Failed****Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive all (5.3.6 (a) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #18**

2023-02-02 11:34

MOT test number

785375947768

Result

✓ Passed

- Advice** Central Oil leak, but not excessive Engine Sump Area (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Lower All Suspension And Steering Components Are Corroded
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

MOT #17

2023-02-02 11:34

MOT test number

582302304029

Result

✗ Failed

- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))
- Advice** Lower All Suspension And Steering Components Are Corroded
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Oil leak, but not excessive Engine Sump Area (8.4.1 (a) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))
- Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #16** 2022-01-13 15:18**MOT test number** 668406010384**Result** ✓ Passed**Advice** Front Coil spring corroded both (5.3.1 (b) (i))**Minor** Front Suspension arm ball joint dust cover severely deteriorated both (5.3.4 (b) (i))**Advice** All over general under body corrosion**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Coil spring worn both (5.3.1 (b) (i))**MOT #15** 2020-12-15 09:02**MOT test number** 281130856475**Result** ✓ Passed**Advice** Sills and floors corroding**MOT #14** 2019-12-14 09:19**MOT test number** 774611117881**Result** ✓ Passed**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**MOT #13** 2018-12-21 09:34**MOT test number** 742222329717**Result** ✓ Passed**MOT #12** 2017-12-29 12:22**MOT test number** 421737634782**Result** ✓ Passed

**MOT #11** 2016-12-19 09:01**MOT test number** 150624694593**Result** ✓ Passed**Advice** Rear Brake pipe slightly corroded both sides (3.6.B.2c)**Advice** Front Direction indicator slightly discoloured both sides (1.4.A.2f)**MOT #10** 2015-12-21 09:03**MOT test number** 849259282928**Result** ✓ Passed**MOT #9** 2015-01-03 08:53**MOT test number** 128783205433**Result** ✓ Passed**MOT #8** 2014-01-04 08:51**MOT test number** 507124604063**Result** ✓ Passed**MOT #7** 2013-01-05 08:50**MOT test number** 589575103067**Result** ✓ Passed**Advice** Front Direction indicator slightly discoloured (1.4.A.2f)**MOT #6** 2012-01-07 09:30**MOT test number** 456787102037**Result** ✓ Passed**MOT #5** 2011-01-07 12:13**MOT test number** 458647601021**Result** ✓ Passed



MOT #4	2010-01-08 09:12
---------------	------------------

MOT test number	683168800040
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2009-01-05 08:59
---------------	------------------

MOT test number	323065109054
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2008-01-08 10:06
---------------	------------------

MOT test number	392348108019
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2007-02-19 11:21
---------------	------------------

MOT test number	773600157059
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-03-01
Last registration	2024-01-16
Complete history	See info



Registration #1	2004-03-01	6 mi
Registration #2	2007-02-19	22.544 mi
Registration #3	2008-01-08	27.197 mi
Registration #4	2009-01-05	30.942 mi
Registration #5	2010-01-08	35.029 mi
Registration #6	2011-01-07	38.508 mi
Registration #7	2012-01-07	42.119 mi
Registration #8	2013-01-05	47.869 mi
Registration #9	2014-01-04	53.510 mi
Registration #10	2015-01-03	59.335 mi
Registration #11	2015-12-21	65.757 mi
Registration #12	2016-01-01	65.757 mi
Registration #13	2016-01-01	65.757 mi
Registration #14	2016-01-01	65.757 mi
Registration #15	2016-01-01	65.757 mi
Registration #16	2016-01-01	65.757 mi
Registration #17	2016-01-01	65.757 mi
Registration #18	2016-01-01	65.757 mi
Registration #19	2016-01-01	65.757 mi
Registration #20	2016-01-01	65.757 mi
Registration #21	2016-01-01	65.757 mi
Registration #22	2016-01-01	65.757 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1130 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	4ZZU499329