



report date: 2024-03-28

General information

Make	VAUXHALL
Model	MERIVA EXCLUSIV AC CDTI
Colour	Blue
Year of manufacture	2014
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	108 BHP
Max. torque	280 Nm at 2.300 rpm
Engine capacity	1.686 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-05
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-14
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	21
Total items failed	2

MOT #10	2023-10-20 10:04
MOT test number	754203388772
Result	✓ Passed
Next expiry date	2024-11-14
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #9	2022-10-28 13:12
MOT test number	519413355255
Result	✓ Passed

MOT #8	2021-11-15 14:04
MOT test number	355319947783
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7	2021-06-02 09:15
MOT test number	545525355537
Result	✓ Passed

**MOT #6** 2020-07-02 09:37**MOT test number** 273507810485**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2020-07-02 09:37**MOT test number** 800802035002**Result** ✗ Failed

- Advice** Nearside Rear Nail in tyre
- Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2019-05-22 12:00**MOT test number** 830193100757**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing and uneven wear (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing and uneven wear (5.2.3 (d) (ii))



MOT #3	2019-05-22 07:46
MOT test number	183175843866
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing and uneven wear (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing and uneven wear (5.2.3 (d) (ii))

MOT #2	2018-06-06 13:58
MOT test number	370796598095
Result	✓ Passed
Advice	Both rear brake discs slightly pitted

MOT #1	2017-05-03 15:03
MOT test number	806964467693
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
14 November 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	14 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YS14UWO
Plate since	2019-06-29
Current registration	 YS14UWO
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-07-17
Last registration	2023-10-20
Complete history	See info



Registration #1	2014-07-17	16 mi
Registration #2	2017-05-03	30.960 mi
Registration #3	2018-06-06	37.431 mi
Registration #4	2019-05-22	46.347 mi
Registration #5	2019-05-22	46.347 mi
Registration #6	2020-07-02	55.927 mi
Registration #7	2020-07-02	55.927 mi
Registration #8	2020-07-02	55.927 mi
Registration #9	2020-07-02	55.927 mi
Registration #10	2020-07-02	55.927 mi
Registration #11	2020-07-02	55.927 mi
Registration #12	2020-07-02	55.927 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1518 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	A17DTI - 2713877LPL