





General information

Make	MINI
Model	MINI ONE D
Colour	Red
Year of manufacture	2013
Top speed	114 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	А







Internet history

Entry 1	
Date	2021-09-11
Pictures	23
Listing price	View report

H NDLER PROTECT Get Covered Today

 \bigcirc



source: cargurus.co.uk



MOT history

MOT expiry date	2023-11-14
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	16
Total items failed	4

MOT test number34374920383ResultNext expiry date2023-11-3
Next expiry date 2023-11-3
Minor Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice Offside Rear Brake pad(s) wearing thin near side still good as new (1.1.13 (a) (ii))
Advice Advise lower dash cover above pedals loose
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor Offside Front Brake hose slightly chafed (1.1.12 (b) (i))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

МОТ #8	2021-11-12 16:38
MOT test number	574623526316
Result	✓ Passed





MOT #7	2021-11-12 08:05	
MOT test number	773423728751	
Result	🗙 Failed	
Fail Offside Rear Service brake excessively binding (1.2.1 (f))		
MOT #6	2021-09-09 11:57	
MOT test number	334883201242	
Result	🗙 Failed	
Fail Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.3)	14 (a) (ii))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Fail Brake performance not tested (1.2.1 (g))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))	
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakene	d (1.1.14 (a) (ii))	
Fail Offside Rear Service brake excessively binding (1.2.1 (f))		

MOT #5		2021-01-22 10:17
MOT test	number	311005558390
Result		Passed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
MOT #4		2020-01-31 12:51

MOT test number	765280613031
Result	✓ Passed
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Offside rear brake disc showing signs of heat	





MOT #3	2019-01-30 17:01
MOT test number	846836755639
Result	✓ Passed
MOT #2	2017-09-29 08:42
MOT test number	513173103967
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal I	imit (4.1.E.2b)
MOT #1	2016-09-29 11:24
MOT test number	278912340244
Result	✓ Passed
Advice Offside Rear tyre slightly worn inside but i	no cords shown





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lashe
Туре	
Damage 2	AMPLE
Damage 2	E CUT D
Date	 *
Category	 amer
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-08-15
Last registration	2022-11-15
Complete history	<u>See info</u>



Registration #1	2013-08-15	9 mi
Registration #2	2016-09-29	34.892 mi
Registration #3	2017-09-29	50.299 mi
Registration #4	2019-01-30	60.554 mi
Registration #5	2020-01-31	76.909 mi
Registration #6	2021-01-22	87.637 mi
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.117 esi





Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles	2
Engine number	70728575