



report date: 2024-03-28

General information

Make	MAZDA
Model	6 TS2
Colour	Silver
Year of manufacture	-
Top speed	132 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	184 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-21
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #14 2023-06-13 10:35

MOT test number 833195190005

Result ✓ Passed

Next expiry date 2024-06-15

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Under-trays obscuring some components
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear exhaust heat shield loose
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #13 2022-06-14 11:05

MOT test number 236572010936

Result ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases y piece (6.1.2 (a))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12**

2021-06-11 13:18

MOT test number

331684832413

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Under-trays obscuring some components
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Front and rear suspension arms corroded
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**MOT #11**

2021-06-11 11:33

MOT test number

327053403078

Result**✗ Failed**

- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Under-trays obscuring some components
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Front and rear suspension arms corroded
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #10

2020-06-16 13:39

MOT test number

191452782290

Result**✓ Passed**

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

**MOT #9** 2019-04-08 06:59**MOT test number** 801667796534**Result** ✓ Passed

Advice Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

Advice Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

MOT #8 2018-03-24 09:15**MOT test number** 292064579952**Result** ✓ Passed

Advice Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (2.4.A.3)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (2.4.A.3)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #7 2017-03-18 10:35**MOT test number** 760805441896**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #6 2016-03-24 15:37**MOT test number** 344314714788**Result** ✓ Passed

Advice Offside Front Brake pad(s) wearing thin INNER PAD WORN (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit CLOSE TO LIMIT (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened INSIDE WORN (3.5.1i)

Advice Nearside Front Tyre worn close to the legal limit CLOSE TO LIMIT (4.1.E.1)

**MOT #5**

2016-03-24 13:15

MOT test number

241446001480

Result

✗ Failed

Advice Nearside Front Tyre worn close to the legal limit CLOSE TO LIMIT (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin INNER PAD WORN (3.5.1g)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Offside Front Tyre worn close to the legal limit CLOSE TO LIMIT (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened INSIDE WORN (3.5.1i)**MOT #4**

2015-03-24 09:03

MOT test number

257453085043

Result

✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt**MOT #3**

2014-03-22 11:03

MOT test number

516361984021

Result

✓ Passed

Notice Under-trays fitted obscuring some underside components**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Items removed from driver's view prior to test**MOT #2**

2013-03-25 11:04

MOT test number

937004983058

Result

✓ Passed

Notice Under-trays fitted obscuring some underside components



MOT #1	2012-10-22 14:59
MOT test number	865516192229
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-11-27
Last registration	2023-06-13
Complete history	See info



Registration #1	2009-11-27	8 mi
Registration #2	2012-10-22	9.857 mi
Registration #3	2013-03-25	10.285 mi
Registration #4	2014-03-22	17.055 mi
Registration #5	2015-03-24	23.609 mi
Registration #6	2016-03-24	30.273 mi
Registration #7	2016-03-24	30.275 mi
Registration #8	2017-03-18	36.334 mi
Registration #9	2018-03-20	42.397 mi
Registration #10	2019-03-20	48.460 mi
Registration #11	2020-03-20	54.523 mi
Registration #12	2021-03-20	60.586 mi
Registration #13	2022-03-20	66.649 mi
Registration #14	2023-03-20	72.712 mi
Registration #15	2023-06-13	78.775 mi
Registration #16	2023-06-13	78.775 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 10836853