




report date: 2024-03-29

General information

Make	MINI
Model	COUNTRYMAN COOPER SD ALL4 AUTO COOPER SD
Colour	White
Year of manufacture	2011
Top speed	120 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-14
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-10
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	17
Total items failed	3

MOT #14	2023-09-08 14:28
MOT test number	819725764469
Result	✓ Passed
Next expiry date	2024-09-10

MOT #13	2022-08-12 15:22
MOT test number	402304730450
Result	✓ Passed
Advice	Coil spring corroded all road springs starting to corrode (5.3.1 (b) (i))

MOT #12	2022-08-12 15:06
MOT test number	509606198325
Result	✗ Failed
DANGEROUS	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Coil spring corroded all road springs starting to corrode (5.3.1 (b) (i))

**MOT #11**

2021-09-01 12:22

**MOT test number**

827202895324

**Result**

✓ Passed

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement rubber D bushes have slight wear (5.3.4 (a) (i))

**Minor** Offside Front Lower Windscreen damaged but not adversely affecting driver's view small stone chip less than 5mm (3.2 (a) (i))

**Advice** Rear Brake pad(s) wearing thin Rear pads getting low 2.5- 3.0 mm will require discs on replacement inner pads are the worst (1.1.13 (a) (ii))

**MOT #10**

2020-09-11 11:24

**MOT test number**

215105009557

**Result**

✓ Passed

**MOT #9**

2019-08-21 14:41

**MOT test number**

665928960188

**Result**

✓ Passed

**Advice** Rear Inner Brake pad(s) wearing thin Inner rear pad worse 3-4mm (1.1.13 (a) (ii))

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge Inner edge very close borderline pass (5.2.3 (e))

**Advice** Rear Brake disc worn, but not excessively wearing with a lip will be required on pad change (1.1.14 (a) (i))

**MOT #8**

2018-08-29 14:55

**MOT test number**

620859673859

**Result**

✓ Passed

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #7**

2017-08-31 12:52

**MOT test number**

960779801328

**Result**

✓ Passed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #6** 2017-08-31 12:52**MOT test number** 629850316594**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2016-09-01 07:12**MOT test number** 981422102751**Result** ✓ Passed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #4** 2016-08-24 08:18**MOT test number** 529017380151**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #3** 2015-08-21 14:30**MOT test number** 895011206307**Result** ✓ Passed**MOT #2** 2014-08-26 14:49**MOT test number** 388078734402**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



MOT #1	2014-08-26 09:27
MOT test number	499078234275
Result	✗ Failed
Fail	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
10 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	10 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>YT61WSV</b>
Plate since	2019-03-29
Current registration	<b>YT61WSV</b>
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-01
Last registration	2023-09-08
Complete history	<a href="#">See info</a>



Registration #1	2011-09-01	21 mi
Registration #2	2014-08-26	23.953 mi
Registration #3	2014-08-26	23.953 mi
Registration #4	2015-08-21	31.621 mi
Registration #5	2016-08-24	39.815 mi
Registration #6	2016-09-01	39.941 mi
Registration #7	2017-08-31	47.446 mi
Registration #8	2017-08-31	47.446 mi
Registration #9	2019-09-01	55.557 mi
Registration #10	2019-09-01	55.557 mi
Registration #11	2019-09-01	55.557 mi
Registration #12	2019-09-01	55.557 mi
Registration #13	2019-09-01	55.557 mi
Registration #14	2019-09-01	55.557 mi
Registration #15	2019-09-01	55.557 mi
Registration #16	2019-09-01	55.557 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1345 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	71457770