



report date: 2024-03-29

General information

| | |
|---------------------|----------------------|
| Make | VOLKSWAGEN |
| Model | TOURAN S TDI DSG DPF |
| Colour | Grey |
| Year of manufacture | 2008 |
| Top speed | 128 mph |
| 0 - 60 mph | 9.8 seconds |
| Gearbox | 6 speed Semi Auto |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 140 BHP |
| Max. torque | 320 Nm at 1.750 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 31.7 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 42.8 mpg |
| CO2 emission | 172 g/km |
| CO2 label | H |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-25 |
| Pictures | 7 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-07 |
| MOT pass rate | 68 % |
| MOT passed | 15 |
| Failed MOT tests | 7 |
| Total advice items | 58 |
| Total items failed | 12 |

| | |
|------------------|------------------|
| MOT #22 | 2023-11-07 10:54 |
| MOT test number | 978902784095 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-07 |

| | |
|-----------------|---|
| MOT #21 | 2023-11-07 08:07 |
| MOT test number | 654980683726 |
| Result | ✗ Failed |
| Fail | Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) |
| Fail | Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) |

| | |
|-----------------|---|
| MOT #20 | 2022-11-08 14:20 |
| MOT test number | 853311090013 |
| Result | ✓ Passed |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

**MOT #19**

2022-03-09 14:35

MOT test number

775575498469

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Shock absorbers has light misting of oil nearside and offside (5.3.2 (b))

MOT #18

2021-03-11 10:07

MOT test number

589557806221

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17

2020-03-13 09:57

MOT test number

715404119439

Result

✓ Passed

MOT #16

2019-02-24 09:26

MOT test number

788076875525

Result

✓ Passed

- Advice** Front tyre worn on edges



MOT #15

2019-02-21 17:27

MOT test number

647221675172

Result

✗ Failed

- Advice

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail

Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**MOT #14**

2019-02-20 12:25

MOT test number

974952048730

Result**✗ Failed**

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear
bush (5.3.4 (a) (i))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13

2019-01-28 11:22

MOT test number

802846143354

Result**✗ Failed**

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered
excessive (5.3.6 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Fail Brake fluid contaminated (1.8 (a))

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt
(5.3.4 (b) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush. (5.3.4 (a) (i))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #12** 2018-01-29 09:58**MOT test number** 856637586004**Result** ✓ Passed**MOT #11** 2017-02-03 09:54**MOT test number** 811884564681**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**MOT #10** 2016-02-11 10:22**MOT test number** 719044305201**Result** ✓ Passed**Advice** Both front tyres wearing on inner edge.**MOT #9** 2016-02-03 11:01**MOT test number** 757646273223**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Advice** Both front tyres wearing on inner edge.**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

**MOT #8** 2015-02-02 10:03**MOT test number** 306213735068**Result** ✓ Passed

- Notice** Front tyres low on edges
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** 1 rear seat folded adult belt not tested o/s
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #7 2015-02-02 10:03**MOT test number** 759333935003**Result** ✗ Failed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** 1 rear seat folded adult belt not tested o/s
- Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Front tyres low on edges
- Pass with rectification** Offside Headlamp aim too high (1.8)

MOT #6 2014-02-24 10:06**MOT test number** 266235254070**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front tyres worn on inside edges
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2013-01-28 16:08**MOT test number** 155298323404**Result** ✓ Passed**MOT #4** 2012-02-13 11:56**MOT test number** 959644442078**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-02-10 16:31**MOT test number** 328861442073**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-02-10 13:27**MOT test number** 397391642071**Result** ✗ Failed**Fail** Front Windscreen wiper not operating automatically when switched on (8.2.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



| | |
|-----------------|------------------|
| MOT #1 | 2011-03-21 15:51 |
| MOT test number | 167930381424 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
7 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 185 |
| MOT expiry date | 7 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | WV08OLP |
| Plate since | 2019-06-29 |
| Current registration | WV08OLP |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 23 |
| First mileage registration | 2008-03-18 |
| Last registration | 2023-11-07 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2008-03-18 | 8 mi |
| Registration #2 | 2011-03-21 | 28.792 mi |
| Registration #3 | 2012-02-10 | 38.500 mi |
| Registration #4 | 2012-02-10 | 38.517 mi |
| Registration #5 | 2012-02-13 | 38.500 mi |
| Registration #6 | 2013-01-28 | 50.223 mi |
| Registration #7 | 2014-02-24 | 64.433 mi |
| Registration #8 | 2015-02-02 | 77.358 mi |
| Registration #9 | 2016-02-03 | 87.800 mi |
| Registration #10 | 2016-02-11 | 88.222 mi |
| Registration #11 | 2017-02-03 | 97.669 mi |
| Registration #12 | 2018-01-29 | 106.632 mi |
| Registration #13 | 2019-01-29 | 116.117 mi |
| Registration #14 | 2019-01-29 | 116.117 mi |
| Registration #15 | 2019-01-29 | 116.117 mi |
| Registration #16 | 2019-01-29 | 116.117 mi |
| Registration #17 | 2019-01-29 | 116.117 mi |
| Registration #18 | 2019-01-29 | 116.117 mi |
| Registration #19 | 2019-01-29 | 116.117 mi |
| Registration #20 | 2019-01-29 | 116.117 mi |
| Registration #21 | 2019-01-29 | 116.117 mi |
| Registration #22 | 2019-01-29 | 116.117 mi |
| Registration #23 | 2019-01-29 | 116.117 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1820 mm |
| Height | 1472 mm |
| Length | 4765 mm |
| Wheel base | 2709 mm |
| Kerb weight | 1671 kg |
| Max. allowed weight | 2090 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |

| | |
|-----------------|------------|
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | BKP 284781 |