






report date: 2024-03-28

#### General information

Make	MERCEDES
Model	S-Class S320
Colour	Blue
Year of manufacture	1999
Top speed	148 mph
0 - 60 mph	8.4 seconds
Gearbox	5 speed automatic

### Engine & fuel consumption

Power	221 BHP
Max. torque	315 Nm at 3.000 rpm
Engine capacity	3.199 сс
Cylinders	6
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	34.5 mpg
Consumption combined	24.6 mpg



CarCheck.co.uk page 1/12



# Internet history

#### Entry 3

Date 2021-10-16

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-09-30
------	------------

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-09-14

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2022-09-22
MOT pass rate	100 %
MOT passed	17
Failed MOT tests	0
Total advice items	19
Total items failed	0

MOT #17		2021-09-10 15:41
MOT test	number	698376853964
Result		✓ Passed
Next exp	iry date	2022-09-22
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c	:))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Nearside front tyre worn slightly on outer edge		
Advice	Offside Front Lower Suspension arm ball joint has slight play rear (5.3.4 (a) (i))	
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #16		2020-09-18 10:05
MOT test	number	132814844609
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Outer (5.2.3 (e))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c	))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #15 2019-08-27 10:43

**MOT test number** 479188421190

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14 2018-09-11 08:28

MOT test number 262947607944

**Result** 
✓ Passed

**Advice** Windscreen damage

MOT #13 2017-08-29 09:26

**MOT test number** 992341897466

Result \rightarrow Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #12 2016-08-31 13:25

**MOT test number** 678351820936

**Result** ✓ Passed

**MOT #11** 2015-09-10 15:01

**MOT test number** 202654562132

**Result** ✓ Passed

MOT #10 2014-09-15 10:51

**MOT test number** 859458554296

**Result** ✓ Passed

MOT #9 2013-09-19 14:32

**MOT test number** 985102863215

**Result** ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #8

MOT test number

Result

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Notice Child seat fitted not allowing full inspection of adult belt

MOT #7

MOT test number

768216561248

Result

Notice Child seat fitted not allowing full inspection of adult belt

MOT #6

MOT test number

Fesult

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #5

MOT test number

724690369242

Result

✓ Passed

MOT #4

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Unable to carry out full test on n/s/r seat belt due to child seat fitted at time of test.

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



**Advice** 

V609GJH report date: 2024-03-28

MOT #3 2007-09-28 16:29 **MOT test number** 443401877297 ✓ Passed Result MOT #2 2006-09-20 12:22 **MOT test number** 844283066272 Result ✓ Passed MOT #1 2005-10-05 15:34 **MOT test number** 214328475217 Result ✓ Passed

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/12



#### Tax & MOT check



X MOT

Expired: 22 September 2022

Tax status Expired at 2 October 2021

Days left 940 days too late

MOT expiry date 22 September 2022

Full MOT history See MOT history

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
*********	
***************************************	
Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	1999-10-26
Last registration	2021-09-10
Complete history	See info



Registration #1	1999-10-26	24 mi
Registration #2	2005-10-05	46.382 mi
Registration #3	2006-09-20	50.811 mi
Registration #4	2007-09-28	54.038 mi
Registration #5	2008-09-15	56.586 mi
Registration #6	2009-09-17	59.367 mi
Registration #7	2010-08-28	61.277 mi
Registration #8	2011-09-23	62.772 mi
Registration #9	2012-09-17	64.554 mi
Registration #10	2013-09-19	66.228 mi
Registration #11	2014-09-15	67.136 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11,177 esi

More info >

page 11/12 CarCheck.co.uk



## Dimensions & weight

Width	1886 mm
Height	1497 mm
Length	5113 mm
Wheel base	2965 mm
Kerb weight	1695 kg

#### Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	11294430551183

CarCheck.co.uk page 12/12