





report date: 2024-03-28

## General information

Make	BMW
Model	X1 SDRIVE18D SE
Colour	Silver
Year of manufacture	2017
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	148 BHP
Max. torque	330 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
<b>Consumption combined</b>	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/12



WL17EVT

report date: 2024-03-28

# Internet history

#### Entry 4

Date 2021-11-24

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 3

Date	2021-10-10	

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

## Entry 2

Date	2021-06-25
Pictures	0

Listing price <u>View report</u>

### source: cargurus.co.uk

#### Entry 1

Date	2021-05-26
Pictures	0

Listing price <u>View report</u>

#### source: theaa.com

CarCheck.co.uk page 2/12



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-31
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	12
Total items failed	4

MOT #8	2023-09-01 12:45
MOT test number	246801092879
Result	✓ Passed
Next expiry date	2024-08-31
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #7	2022-09-01 10:11
MOT test number	107225905425
Result	<b>✓</b> Passed
MOT #6	2022-03-03 09:41
MOT test number	188333837972
Result	<b>✓</b> Passed
MOT #5	2021-06-22 11:35
MOT test number	735101356609
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



**MOT #4** 

WL17EVT report date: 2024-03-28

2021-06-16 09:05

MOT test number 236776460908

**Result** ✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor** Offside Front Side repeater with a multiple light source up to 1/2 not functioning slight damage to side repeater in mirror not all working (4.4.1 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2021-06-07 14:52

MOT test number 855805601509

**Result** X Failed

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor** Offside Front Side repeater with a multiple light source up to 1/2 not functioning slight damage to side repeater in mirror not all working (4.4.1 (a) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2021-04-23 15:07

**MOT test number** 543102400124

**Result** X Failed

Advice Offside Front slight damage to side repeater in mirror not all working

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Nail in tyre

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



MOT #1 2020-07-23 09:22

**MOT test number** 951246889431

**Result** ✓ Passed

Advice

**COVID-19 6 MONTH EXTENSION** 

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	31 August 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



# Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did check it in the premium report and see all owner registrations. Download the full report	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	*****
Current registration	ZIS UK
Plate since	m.n.n
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-07-31
Last registration	2023-09-01
Complete history	See info



Registration #1	2017-07-31	18 mi
Registration #2	2021-04-23	28.692 mi
Registration #3		0.77 ss
Registration #4	2021-06-07	28.698 mi
Registration #5	2021-06-16	28.700 mi
Registration #6	2021-06-22	28.842 mi
Registration #7		11.777 es
Registration #8		11.777 ea
Registration #9		0.77 ss
Registration #10		11.777 es
Registration #11		0.0746
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1821 mm
Height	1598 mm
Length	4439 mm
Wheel base	2670 mm
Kerb weight	1430 kg
Max. allowed weight	2015 kg

# Additional information

Fuel tank capacity	51	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	e 12/12

Number of axles 2

Engine number 76629901