





report date: 2024-03-28

General information

Make	FIAT
Model	500 LOUNGE
Colour	Red
Year of manufacture	2017
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date	2021-01-29	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-07
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	23
Total items failed	0

MOT #7	2024-03-11 15:51
MOT test number	559414576547
Result	✓ Passed
Next expiry date	2025-04-07
Advice Nearside Front Macpherson strut pin or bush worn but not resulting in strut mount has lift (5.3.4 (a) (i))	n excessive movement top
Advice Nearside Rear Nail in tyre	
Advice Brake cable damaged but not to excess outer cable cover (1.1.15 (a))
Advice Offside Front Tyre worn close to legal limit/worn on edge tyre worn of	n inside edge (5.2.3 (e))
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))	
Advice Nearside main beam holder insercure	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Fluid leak, but not excessive coolant leak from thermostat housing (8	3.4.1 (a) (i))

CarCheck.co.uk page 3/12



MOT #6 2024-03-06 12:15

MOT test number 616640067826

Result X Failed

Advice Nearside main beam holder insercure

MAJOR Nearside Front Suspension arm pin or bush excessively worn rear wishbone bush (5.3.4 (a) (i))

Advice Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement top strut mount has lift (5.3.4 (a) (i))

Advice Brake cable damaged but not to excess outer cable cover (1.1.15 (a))

Advice Nearside Rear Nail in tyre

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge tyre worn on inside edge (5.2.3 (e))

Advice Fluid leak, but not excessive coolant leak from thermostat housing (8.4.1 (a) (i))

MOT #5 2023-03-30 14:00

MOT test number 290047812429

Result
✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2022-03-10 10:05

MOT test number 321769485306

Result
✓ Passed

Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



MOT #3 2021-04-08 14:33 **MOT test number** 534441483228 ✓ Passed Result MOT #2 2020-10-01 16:16 **MOT test number** 424660632322 Result ✓ Passed MOT #1 2020-06-21 05:56 596876204650 **MOT test number** Result ✓ Passed **Advice COVID-19 6 MONTH EXTENSION**

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	7 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
manus .	

manus .	

	More info >
Plate changes	
Coo in this shock if this FIAT had different number plates	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK NEW
Fiate since	
Current registration	UK WE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-06-29
Last registration	2024-03-11
Complete history	See info



Designation #1	2017 06 20	7 mi
Registration #1	2017-06-29	7 mi
Registration #2	2020-10-01	20.100 mi
Registration #3		11.777 es
Registration #4	2021-04-08	20.105 mi
Registration #5		9.70 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		10.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	66%
Children	49%
Pedestrian	53%
Safety systems	27%
Overall rating	52%
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1345 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles Carcheck.co.uk	2 page 12/12