





report date: 2024-03-29

General information

Make	MAZDA
Model	3 TAKARA
Colour	Blue
Year of manufacture	2009
Top speed	114 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

E ~	+	, 1
	ILI V	, .

Entry 1	
Date	2021-06-18
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-01
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	21
Total items failed	6

MOT #17	2023-06-16 12:11	
MOT test number	340827534392	
Result	✓ Passed	
Next expiry date 2024-07-03		
Minor Headlamp lens slightly defective Nearside & Offside (4.1.1 (b) (i))		
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		

MOT #16		2023-06-16 12:11
MOT test number		673920273418
Result		X Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Minor Headlamp lens slightly defective Nearside & Offside (4.1.1 (b) (i))		

MOT #15	2022-06-23 10:16
MOT test number	659200480543
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #14 2022-06-23 08:30

MOT test number 998931585517

Result X Failed

Fail Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

MOT #13 2021-07-02 11:20

MOT test number 732397046065

Result ✓ Passed

MOT #12 2021-07-01 09:26

MOT test number 914564911820

Result X Failed

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #11 2021-02-19 12:55

MOT test number 363873594798

Result
✓ Passed

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #10 2021-02-17 16:19 **MOT** test number 155514999675 Result × Failed Fail Offside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i)) Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Fail Nearside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice**

MOT #9		2020-02-11 09:24
MOT test	number	579557518594
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2019-02-15 16:2
MOT test	number 84328892542
Result	✓ Passe
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge only on both edges (5.2.3 (e))
Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge only (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inner edge only (5.2.3 (e))

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #7 2018-02-15 17:26

MOT test number 148112128813

MOT #6 2017-02-16 09:45

MOT test number 390753360260

Result Passed

Advice Offside Rear Tyre worn close to the legal limit wearing inner edge uneven (4.1.E.1)

MOT #5 2016-02-12 08:58

MOT test number 972934879976

Advice Offside Rear tyre worn uneven inner edge

MOT #4 2015-02-16 14:42

MOT test number 336077945091

Result
✓ Passed

MOT #3 2014-02-13 11:55

MOT test number 889394844090

Result \(\sqrt{Passed} \)

MOT #2 2013-02-14 15:12

MOT test number 415995643008

Result ✓ Passed

MOT #1 2012-02-13 11:02

MOT test number 106344642035

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	1 July 2024
Full MOT history	See MOT history

Tax calculation

Vahisla slags	40
Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

_	
Owner	history
OWITCH	HISCOLY

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-09
Last registration	2023-06-16
Complete history	See info



Registration #1	2009-03-09	14 mi
Registration #2	2012-02-13	28.480 mi
Registration #3	2013-02-14	36.831 mi
Registration #4	2014-02-13	45.286 mi
Registration #5	2015-02-16	48.900 mi
Registration #6	2016-02-12	57.479 mi
Registration #7	2017-02-16	64.532 mi
Registration #8	2018-02-15	70.784 mi
Registration #9	2019-02-15	75.759 mi
Registration #10	2020-02-11	77.437 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 ms

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4440 mm
Wheel base	2640 mm
Kerb weight	1275 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z6 733311

CarCheck.co.uk page 13/13