



report date: 2024-03-28

## General information

Make	VOLVO
Model	C30 D DRIVE SE
Colour	Black
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





## Internet history

### Entry 3

Date 2022-02-27

Pictures 17

Listing price [View report](#)




source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2

Date 2022-02-07

Pictures 2

Listing price [View report](#)





source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date 2021-07-31

Pictures 7

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-12
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	28
Total items failed	9

MOT #17	2023-10-27 08:27
MOT test number	125063710128
Result	✓ Passed
Next expiry date	2024-11-12

MOT #16	2022-11-10 13:35
MOT test number	609195010609
Result	✓ Passed

MOT #15	2021-11-13 11:00
MOT test number	976515429518
Result	✓ Passed

**MOT #14**

2021-05-19 12:19

**MOT test number**

231037023634

**Result**

✓ Passed

- Advice** Under trays obscuring testable items
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Lower Dust cover missing from brake caliper
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #13**

2021-05-17 13:48

**MOT test number**

430844576830

**Result**

✗ Failed

- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Position lamp with a multiple light source more than 1/2 not functioning Side light and side marker light not functioning (4.2.1 (a) (ii))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Offside Front Lower Dust cover missing from brake caliper
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Under trays obscuring testable items
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2020-11-18 11:50**MOT test number** 716342054161**Result** ✓ Passed**MOT #11** 2019-04-23 14:51**MOT test number** 531873577206**Result** ✓ Passed**MOT #10** 2019-04-16 10:45**MOT test number** 682351837357**Result** ✗ Failed**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #9** 2018-04-30 12:37**MOT test number** 201728727334**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #8** 2018-04-30 12:37**MOT test number** 942065512800**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear Parking brake lever has little reserve travel (3.1.6b)

**MOT #7** 2017-05-19 14:59**MOT test number** 802503681829**Result** ✓ Passed**MOT #6** 2016-06-24 08:44**MOT test number** 664259689140**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-06-23 18:37**MOT test number** 900585402726**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Registration plate lamp not working both (1.1.C.1d)**MOT #4** 2015-03-21 11:26**MOT test number** 955260485028**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2015-03-21 11:26**MOT test number** 179270185493**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #2	2014-03-24 13:59
MOT test number	498993984007
Result	✓ Passed

MOT #1	2013-08-05 14:36
MOT test number	895887813243
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
12 November 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	12 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>FY60XJG</b>
Plate since	2024-03-28
Current registration	<b>FY60XJG</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-09-27
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	2010-09-27	27 mi
Registration #2	2013-08-05	60.093 mi
Registration #3	2014-03-24	68.293 mi
Registration #4	2015-03-21	76.756 mi
Registration #5	2016-06-23	83.820 mi
Registration #6	2016-06-24	83.820 mi
Registration #7	2017-05-19	84.224 mi
Registration #8	2018-04-30	84.594 mi
Registration #9	2018-04-30	84.594 mi
Registration #10	2019-04-16	84.686 mi
Registration #11	2019-05-20	85.277 mi
Registration #12	2019-05-20	85.277 mi
Registration #13	2019-05-20	85.277 mi
Registration #14	2019-05-20	85.277 mi
Registration #15	2019-05-20	85.277 mi
Registration #16	2019-05-20	85.277 mi
Registration #17	2019-05-20	85.277 mi
Registration #18	2019-05-20	85.277 mi
Registration #19	2019-05-20	85.277 mi
Registration #20	2019-05-20	85.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1382 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	957548