





report date: 2024-03-29

General information

Make	BMW
Model	X1 XDRIVE25D M SPORT
Colour	Grey
Year of manufacture	2014
Top speed	127 mph
0 - 60 mph	6.8 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	215 BHP
Max. torque	450 Nm at 1.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry	1
-------	---

LIICI Y I	
Date	2021-01-29
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-05
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	18
Total items failed	3

MOT #10	2023-10-06 07:19
MOT test number	531385847897
Result	✓ Passed
Next expiry date	2024-10-05

MOT #9	2023-10-03 13:15
MOT test number	318036865534
Result	X Failed
Fail Offside Rear Service brake excessively binding (1.2.1 (f))	

MOT #8	2023-03-10 18:49
MOT test number	107314369787
Result	✓ Passed
Advice Offside Front Suspension arm pin or bush worn but not resulting i (5.3.4 (a) (i))	n excessive movement rear bush
Advice Nearside Front Suspension arm pin or bush worn but not resulting bushes (5.3.4 (a) (i))	g in excessive movement rear

CarCheck.co.uk page 3/12



 MOT #7
 2022-03-07 15:40

 MOT test number
 841287054146

 Result
 ✓ Passed

Advice Nearside Front Tyre slightly damaged Outer sidewall (5.2.3 (d) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2022-03-07 09:07

MOT test number 673120233782

Result X Failed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre slightly damaged Outer sidewall (5.2.3 (d) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Inner sidewall (5.2.3 (d) (i))

MOT #5 2021-03-09 15:01

MOT test number 284167097468

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/12



MOT #4 2021-02-25 14:30 298418406747 **MOT** test number Result × Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

462747475046

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Tyre worn close to legal limit/worn on edge Both side (5.2.3 (e))

Advice (a) (i))

Front Suspension arm pin or bush worn but not resulting in excessive movement Both side (5.3.4 (a) (i))

(a) (i))	
MOT #2	2019-01-23 08:44
MOT test number	754936907741
Result	✓ Passed
MOT #1	2018-02-01 19:21
MOT test number	574798450027
Result	✓ Passed
Advice ENGINE COVER AND UNDER TRAY FITTED	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	history
OWITCH	IIIJCOI y

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I		ve?

	More info	,
Plate changes	More into	/
See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-11-28
Last registration	2023-10-06
Complete history	See info



2014-11-28	22 mi
2018-02-01	37.182 mi
2019-01-23	48.783 mi
2020-01-07	63.283 mi
	11.777 es
2021-02-25	71.740 mi
	11.777 es
	D.777 es
	2018-02-01 2019-01-23 2020-01-07

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1798 mm
Height	1545 mm
Length	4477 mm
Wheel base	2760 mm
Kerb weight	1595 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	61
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 89858965