



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D S
Colour	Blue
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 2



Date	2023-11-19
Pictures	4
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-07-30
Pictures	31
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-28
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	17
Total items failed	7

MOT #15	2023-11-29 16:17
MOT test number	651782371149
Result	✓ Passed
Next expiry date	2024-11-28
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2023-03-14 12:45
MOT test number	413364818354
Result	✓ Passed
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside front marker light not working
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Nail in tyre
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13**

2023-03-08 15:22

**MOT test number**

407770664883

**Result****✗ Failed****Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Nail in tyre**Fail** Nearside Front Body panel damaged and likely to cause injury Wheel arch (6.2.1 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside front marker light not working**MOT #12**

2022-02-25 14:39

**MOT test number**

731733700126

**Result****✓ Passed****Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #11**

2021-03-11 14:54

**MOT test number**

590402612799

**Result****✓ Passed**

**MOT #10** 2021-03-09 14:27**MOT test number** 650928657125**Result** ✗ Failed**Fail** Nearside Front Lower Sub-frame pin or bush excessively worn rear mounted(marked) (5.3.4 (a) (i))**Fail** Nearside Rear Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Lower Sub-frame pin or bush excessively worn rear mounted(marked) (5.3.4 (a) (i))**MOT #9** 2020-03-02 11:52**MOT test number** 537948844178**Result** ✓ Passed**MOT #8** 2019-03-11 11:51**MOT test number** 623057358030**Result** ✓ Passed**MOT #7** 2019-03-11 11:51**MOT test number** 550952759421**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a))**MOT #6** 2018-03-05 16:11**MOT test number** 870487770754**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Front tyre slightly worn inner edge



<b>MOT #5</b>	2017-03-08 10:40
---------------	------------------

<b>MOT test number</b>	578166590108
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2016-03-08 10:29
---------------	------------------

<b>MOT test number</b>	983158027159
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2015-03-13 12:03
---------------	------------------

<b>MOT test number</b>	116782375066
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2014-03-05 11:28
---------------	------------------

<b>MOT test number</b>	286544064065
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	O/s/f tyre bald on inner shoulder
---------------	-----------------------------------

<b>MOT #1</b>	2013-03-07 12:15
---------------	------------------

<b>MOT test number</b>	909366663000
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
28 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	28 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 YX10XAW
Plate since	2019-03-28
Current registration	 YX10XAW
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-17
Last registration	2023-11-29
Complete history	<a href="#">See info</a>



Registration #1	2010-03-17	23 mi
Registration #2	2013-03-07	36.281 mi
Registration #3	2014-03-05	46.284 mi
Registration #4	2015-03-13	58.374 mi
Registration #5	2016-03-08	69.797 mi
Registration #6	2017-03-08	78.646 mi
Registration #7	2018-03-05	87.590 mi
Registration #8	2019-03-11	97.724 mi
Registration #9	2019-03-11	97.724 mi
Registration #10	2020-03-05	107.858 mi
Registration #11	2021-03-05	117.992 mi
Registration #12	2022-03-05	128.126 mi
Registration #13	2023-03-05	138.260 mi
Registration #14	2024-03-05	148.394 mi
Registration #15	2025-03-05	158.528 mi
Registration #16	2026-03-05	168.662 mi
Registration #17	2027-03-05	178.796 mi
Registration #18	2028-03-05	188.930 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1446 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	727050
---------------	--------