



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | NISSAN |
| Model | PRIMERA S |
| Colour | Grey |
| Year of manufacture | 2004 |
| Top speed | 121 mph |
| 0 - 60 mph | 11.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 114 BHP |
| Max. torque | 163 Nm at 4.000 rpm |
| Engine capacity | 1.769 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 29.4 mpg |
| Consumption extra urban | 46.3 mpg |
| Consumption combined | 38.2 mpg |
| CO2 emission | 177 g/km |
| CO2 label | I |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-02-06 |
| Pictures | 1 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-19 |
| MOT pass rate | 63 % |
| MOT passed | 17 |
| Failed MOT tests | 10 |
| Total advice items | 56 |
| Total items failed | 14 |

MOT #27 2024-02-01 14:34

MOT test number 845486419788

Result ✓ Passed

Next expiry date 2025-02-19

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear seat belts cant be tested because the seat are down
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Fuel Pipe/s corroded
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #26**

2024-01-31 12:11

MOT test number

345264345501

Result**✗ Failed**

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Fuel Pipe/s corroded

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Rear seat belts cant be tested because the seat are down

Advice Rear Coil spring corroded (5.3.1 (b) (i))

MOT #25

2023-02-16 11:57

MOT test number

855542797772

Result**✓ Passed**

Advice Nearside Rear Fuel Pipe/s corroded

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #24

2023-02-16 11:57

MOT test number

484026187660

Result**✗ Failed**

Advice Nearside Rear Fuel Pipe/s corroded

Pass with rectification Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #23**

2022-01-28 10:13

MOT test number

920257831568

Result

✓ Passed

Advice

Sill covers fitted

Advice

Vehicle structure is corroded but structural rigidity is not significantly reduced both inner sills (6.1.1 (c) (i))

Advice

Engine covers & undertrays fitted

Advice

Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #22

2021-02-02 14:44

MOT test number

906676316277

Result

✓ Passed

Advice

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice

Engine covers & undertrays fitted

Advice

Sill covers fitted

MOT #21

2021-01-28 10:10

MOT test number

554801419209

Result

✗ Failed

Fail

Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice

Engine covers & undertrays fitted

Fail

Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice

Sill covers fitted

**MOT #20**

2020-02-20 14:45

MOT test number

434671576807

Result

✓ Passed

Advice

Offside Front Tyre worn close to legal limit/worn on edge worn on inside edge (5.2.3 (e))

MOT #19

2020-02-11 17:35

MOT test number

961908199233

Result

✗ Failed

Advice

Offside Front tyre perished on outer sidewall

Advice

Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice

Offside Front tyre worn on inner edge

Fail

Offside Front Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii))

Advice

Offside Front window mechanism defective

Fail

Offside Front Service brake excessively binding (1.2.1 (f))

MOT #18

2019-02-14 14:21

MOT test number

781682681414

Result

✓ Passed

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17** 2019-01-31 12:48**MOT test number** 766265879945**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #16** 2017-12-05 11:01**MOT test number** 964608875179**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit o/s and n/s on limit and perished (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #15** 2017-12-05 10:39**MOT test number** 137581214943**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Rear Tyre worn close to the legal limit o/s and n/s on limit and perished (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2016-11-15 11:52**MOT test number** 992095334303**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit o/s and n/s raised edge tread and perished (4.1.E.1)

**MOT #13** 2016-11-14 10:54**MOT test number** 132324638808**Result** ✗ Failed**Advice** Rear Tyre worn close to the legal limit o/s and n/s raised edge tread and perished (4.1.E.1)**Fail** Nearside Front Anti-lock braking system component excessively damaged ring (3.4.2)**MOT #12** 2015-11-30 09:55**MOT test number** 888618019324**Result** ✓ Passed**Advice** Tyre worn close to the legal limit both rears (4.1.E.1)**MOT #11** 2014-11-17 09:52**MOT test number** 128851024346**Result** ✓ Passed**Notice** Both rear tyres cracked**MOT #10** 2013-11-25 13:58**MOT test number** 549489423350**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2013-11-25 13:58**MOT test number** 398629423372**Result** ✗ Failed**Pass with rectification** Front Direction indicator incorrect colour (1.4.A.2f)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2012-12-06 10:01**MOT test number** 167501642334**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2011-11-21 14:06**MOT test number** 708525621329**Result** ✓ Passed**MOT #6** 2011-11-21 11:16**MOT test number** 548945221365**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2010-12-08 10:22**MOT test number** 493162040405**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2010-12-08 10:22**MOT test number** 580312040337**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



| | |
|-----------------|---|
| MOT #3 | 2009-12-07 09:40 |
| MOT test number | 123971449343 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |

| | |
|-----------------|------------------|
| MOT #2 | 2008-12-11 12:23 |
| MOT test number | 630816348308 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #1 | 2007-11-26 09:50 |
| MOT test number | 432590737336 |
| Result | ✓ Passed |
| Advice | Rear Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
19 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 93 |
| MOT expiry date | 19 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2023-03-29 |
| Current registration | ***** |
| Plate since | 2023-03-29 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 27 |
| First mileage registration | 2004-12-09 |
| Last registration | 2024-02-01 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2004-12-09 | 26 mi |
| Registration #2 | 2007-11-26 | 19.585 mi |
| Registration #3 | 2008-12-11 | 23.303 mi |
| Registration #4 | 2009-12-07 | 26.116 mi |
| Registration #5 | 2010-12-08 | 29.216 mi |
| Registration #6 | 2011-11-21 | 31.705 mi |
| Registration #7 | 2011-11-21 | 31.705 mi |
| Registration #8 | 2012-12-06 | 34.653 mi |
| Registration #9 | 2013-11-25 | 36.972 mi |
| Registration #10 | 2014-11-17 | 39.194 mi |
| Registration #11 | 2015-11-30 | 41.377 mi |
| Registration #12 | 2016-11-14 | 43.127 mi |
| Registration #13 | 2016-11-15 | 43.127 mi |
| Registration #14 | 2017-12-05 | 44.429 mi |
| Registration #15 | 2018-05-22 | 45.377 mi |
| Registration #16 | 2018-05-22 | 45.377 mi |
| Registration #17 | 2018-05-22 | 45.377 mi |
| Registration #18 | 2018-05-22 | 45.377 mi |
| Registration #19 | 2018-05-22 | 45.377 mi |
| Registration #20 | 2018-05-22 | 45.377 mi |
| Registration #21 | 2018-05-22 | 45.377 mi |
| Registration #22 | 2018-05-22 | 45.377 mi |
| Registration #23 | 2018-05-22 | 45.377 mi |
| Registration #24 | 2018-05-22 | 45.377 mi |
| Registration #25 | 2018-05-22 | 45.377 mi |
| Registration #26 | 2018-05-22 | 45.377 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

| | |
|-------------|---------|
| Width | 1760 mm |
| Height | 1488 mm |
| Length | 4567 mm |
| Wheel base | 2680 mm |
| Kerb weight | 1361 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 62 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of axles | 2 |
| Engine number | 330821 |