

Ford



## General information

FORD
FIESTA EDGE
White
2010
104 mph
13.3 seconds
5 speed Manual
F 2 1

### Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm at 4.200 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D







# Internet history

Entry 1		
Date		


2021-02-08

16

Listing price

Pictures

View report



source: yesauto.com



## MOT history

MOT expiry date	2024-12-11
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	9
Total items failed	8

MOT #16	2023-12-12 10:25
MOT test number	761749261034
Result	✓ Passed
Next expiry date	2024-12-11

MOT #15	2023-12-07 14:59
MOT test number	479086572356
Result	🗙 Failed
<b>Fail</b> Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
<b>Fail</b> Nearside Front Position lamp not working (4.2.1 (a) (ii))	
<b>Fail</b> Offside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))	
<b>Fail</b> Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #14	2022-12-07 13:38
MOT test number	509219524452
Result	✓ Passed



MOT #13	2022-01-27 08:39
MOT test number	279299907150
Result	✓ Passed
Advice All direction indicators slightly discoloured (4.4.3 (a))	
<b>Advice</b> Front Brakes imbalanced requirements only just met. It would appear requires adjustment or repair. (1.2.1 (b) (i))	r that the braking system

MOT #12	2021-02-05 16:36
MOT test number	772805852961
Result	✓ Passed

MOT #11	2020-04-02 12:07
MOT test number	492312692325
Result	✓ Passed

MOT #10	2020-04-02 08:54
MOT test number	316253091716
Result	🗙 Failed
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #9		2019-04-11 09:20
MOT test	number	397155041203
Result		✓ Passed
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge tread (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Outer Tyre slightly damaged/cracking or perishing tread (5.2.3 (d)	(ii))

YH60AAV

report date: 2024-03-29





MOT #8	2018-04-19 09:23
MOT test number	301139344105
Result	✓ Passed
Advice Both rear tyres showing signs of tearing on outer treads	
MOT #7	2017-03-29 12:15
MOT test number	702562704870
Result	✓ Passed
МОТ #6	2017-03-29 09:48
MOT test number	772002272555
Result	🗙 Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #5		2016-04-21 12:01
MOT test	number	254549237281
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2015-04-08 12:11
MOT test number	316968695087
Result	✓ Passed
MOT #3	2014-04-29 14:05

MOT test number	659979614105
Result	✓ Passed





MOT #2	2014-01-23 10:09
MOT test number	916463024069
Result	✓ Passed
MOT #1	2013-09-26 10:34
MOT test number	399319663469
Result	✓ Passed



Tax & MOT check

✓ Taxed	мот
1 December 2024	Expires: 11 December 2024 Valid until 1 December
Days left	216
MOT expiry date	11 December 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Carrent registration Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-29
Last registration	2023-12-12
Complete history	See info



Registration #1	2010-09-29	20 mi
Registration #2	2013-09-26	7.499 mi
Registration #3	2014-01-23	7.670 mi
Registration #4	2014-04-29	7.906 mi
Registration #5	2015-04-08	13.684 mi
Registration #6	2016-04-21	21.381 mi
Registration #7	2017-03-29	26.938 mi
Registration #8	2017-03-29	26.938 mi
Registration #9	2018-04-19	34.485 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.117 mi





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1490 kg
Additional information	
Fuel tank capacity	42
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	AU64848