



Mercedes-Benz

DE09JNO

report date: 2024-03-29

General information

| | |
|---------------------|--------------------------|
| Make | MERCEDES-BENZ |
| Model | SPRINTER 311 CDI LWB P/V |
| Colour | White |
| Year of manufacture | - |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------|---------------------|
| Power | 109 BHP |
| Max. torque | 280 Nm at 1.600 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |



LABEL UNKNOWN

**MOT history**

| | |
|-------------------------|---|
| MOT #14 | 2023-01-04 19:36 |
| MOT test number | 653598774943 |
| Result | ✓ Passed |
| Next expiry date | 2024-01-17 |
| Advice | Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i)) |
| Advice | Rear Coil spring corroded both side (5.3.1 (b) (i)) |
| Advice | Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |

| | |
|------------------------|--|
| MOT #13 | 2023-01-04 18:51 |
| MOT test number | 779309623059 |
| Result | ✗ Failed |
| Advice | Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |
| Advice | Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i)) |
| Fail | Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e)) |
| Fail | Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Advice | Rear Coil spring corroded both side (5.3.1 (b) (i)) |

| | |
|------------------------|---|
| MOT #12 | 2022-01-18 18:19 |
| MOT test number | 508713331016 |
| Result | ✓ Passed |
| Advice | Brake disc worn, but not excessively all four (1.1.14 (a) (i)) |
| Advice | Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e)) |
| Advice | Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i)) |
| Advice | Front Brake pad(s) wearing thin both side (1.1.13 (a) (ii)) |
| Advice | Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

**MOT #11** 2022-01-18 18:19**MOT test number** 115139753140**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake disc worn, but not excessively all four (1.1.14 (a) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front Brake pad(s) wearing thin both side (1.1.13 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10 2019-04-30 10:59**MOT test number** 147713000526**Result** ✓ Passed**MOT #9** 2019-04-30 10:59**MOT test number** 455177999284**Result** ✗ Failed

- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))

MOT #8 2018-04-02 11:17**MOT test number** 826749485342**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7 2017-03-08 08:49**MOT test number** 113845609412**Result** ✓ Passed

**MOT #6** 2016-04-12 07:36**MOT test number** 244854373570**Result** ✓ Passed**MOT #5** 2016-04-08 08:00**MOT test number** 831360065086**Result** ✗ Failed

- Fail** Nearside Steering rack gaiter split (2.2.D.2d)
- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Offside Rear reflector excessively deteriorated so that its function is impaired (1.5.1c)
- Fail** Rear parking (secondary) brakes imbalanced (3.7.B.6b)

MOT #4 2015-03-31 08:47**MOT test number** 728580295008**Result** ✓ Passed

- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #3 2014-03-17 09:27**MOT test number** 696916674033**Result** ✓ Passed

- Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)



| | |
|-----------------|---|
| MOT #2 | 2013-04-10 16:37 |
| MOT test number | 267070903404 |
| Result | ✓ Passed |
| Advice | Offside Suspension arm has slight play in a ball joint (2.4.G.2) |
| Advice | Nearside Suspension arm has slight play in a ball joint (2.4.G.2) |

| | |
|-----------------|------------------|
| MOT #1 | 2012-04-03 08:55 |
| MOT test number | 765044792048 |
| Result | ✓ Passed |



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  DE09JNO |
| Plate since | 2019-03-29 |
| Current registration |  DE09JNO |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2009-04-15 |
| Last registration | 2023-01-04 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2009-04-15 | 12 mi |
| Registration #2 | 2012-04-03 | 44.242 mi |
| Registration #3 | 2013-04-10 | 59.882 mi |
| Registration #4 | 2014-03-17 | 69.531 mi |
| Registration #5 | 2015-03-31 | 81.889 mi |
| Registration #6 | 2016-04-08 | 93.565 mi |
| Registration #7 | 2016-04-12 | 93.565 mi |
| Registration #8 | 2017-03-08 | 99.990 mi |
| Registration #9 | 2018-03-08 | 101.990 mi |
| Registration #10 | 2019-03-08 | 103.990 mi |
| Registration #11 | 2020-03-08 | 105.990 mi |
| Registration #12 | 2021-03-08 | 107.990 mi |
| Registration #13 | 2022-03-08 | 109.990 mi |
| Registration #14 | 2023-03-08 | 111.990 mi |
| Registration #15 | 2024-03-08 | 113.990 mi |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1960 mm |
| Height | 3050 mm |
| Length | 6940 mm |
| Kerb weight | 2280 kg |
| Max. allowed weight | 3500 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 75 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |

Number of axles

2

Engine number

64698551773317