



YAIIEGZ

report date: 2024-03-29

General information

| | |
|---------------------|--------------------------|
| Make | MINI |
| Model | COUNTRYMAN COOPER COOPER |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 118 mph |
| 0 - 60 mph | 10.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|----------------------|---------------------|
| Power | 122 BHP |
| Max. torque | 160 Nm at 4.250 rpm |
| Engine capacity | 1.600 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption combined | 46.3 mpg |
| CO2 emission | 140 g/km |
| CO2 label | E |







Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-12-02 |
| Pictures | 16 |
| Listing price | View report |



source: [autotrader.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-01-31 |
| Pictures | 12 |
| Listing price | View report |



source: [cargurus.co.uk](#)

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2024-11-27 |
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 11 |
| Total items failed | 4 |

| | |
|-------------------------|------------------|
| MOT #13 | 2023-11-27 17:08 |
| MOT test number | 984403635879 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-27 |

| | |
|------------------------|------------------|
| MOT #12 | 2022-11-28 12:11 |
| MOT test number | 451471779683 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #11 | 2021-10-04 09:19 |
| MOT test number | 112357503793 |
| Result | ✓ Passed |

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

| | |
|------------------------|------------------|
| MOT #10 | 2020-09-23 15:18 |
| MOT test number | 728783473241 |
| Result | ✓ Passed |



| | |
|------------------------|-----------------------------------------------------------|
| MOT #9 | 2020-09-23 13:18 |
| MOT test number | 249443132738 |
| Result | ✗ Failed |
| Fail | Nearside Front Position lamp not working (4.2.1 (a) (ii)) |

| | |
|------------------------|-----------------------------------------------------------------------------|
| MOT #8 | 2020-09-01 16:37 |
| MOT test number | 822467851430 |
| Result | ✗ Failed |
| Advice | Coolant leak |
| Fail | Nearside Front Position lamp not working (4.2.1 (a) (ii)) |
| Advice | Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Fail | Front passenger door cannot be opened from inside the vehicle (6.2.3 (a)) |
| Advice | Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

| | |
|------------------------|-------------------------------------------------------------------------------------------------|
| MOT #7 | 2019-04-19 13:24 |
| MOT test number | 158360951248 |
| Result | ✓ Passed |
| Advice | Offside Rear Nail in tyre |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened both worn (1.1.14 (a) (ii)) |

| | |
|------------------------|-------------------------------------------------------------|
| MOT #6 | 2018-04-19 11:24 |
| MOT test number | 691898678831 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |

**MOT #5** 2017-04-25 12:14**MOT test number** 537912566332**Result** ✓ Passed**MOT #4** 2016-08-20 10:17**MOT test number** 803532091748**Result** ✓ Passed**MOT #3** 2016-08-19 10:23**MOT test number** 748105741353**Result** ✗ Failed

Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure inner sidewall (4.1.D.1b)

MOT #2 2015-08-17 11:57**MOT test number** 660411771968**Result** ✓ Passed**MOT #1** 2014-08-22 10:56**MOT test number** 188354034206**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
27 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 278 |
| MOT expiry date | 27 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|------------------------------------------------|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this MINI had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2011-08-22 |
| Last registration | 2023-11-27 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2011-08-22 | 28 mi |
| Registration #2 | 2014-08-22 | 24.318 mi |
| Registration #3 | 2015-08-17 | 37.475 mi |
| Registration #4 | 2016-08-19 | 51.564 mi |
| Registration #5 | 2016-08-20 | 51.565 mi |
| Registration #6 | 2017-04-25 | 60.508 mi |
| Registration #7 | 2018-04-19 | 68.660 mi |
| Registration #8 | 2019-04-19 | 75.502 mi |
| Registration #9 | 2020-04-19 | 82.344 mi |
| Registration #10 | 2021-04-19 | 89.186 mi |
| Registration #11 | 2022-04-19 | 96.028 mi |
| Registration #12 | 2023-04-19 | 102.870 mi |
| Registration #13 | 2024-04-19 | 109.712 mi |
| Registration #14 | 2025-04-19 | 116.554 mi |
| Registration #15 | 2026-04-19 | 123.396 mi |
| Registration #16 | 2027-04-19 | 130.238 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 84% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1789 mm |
| Height | 1577 mm |
| Length | 4097 mm |
| Kerb weight | 1265 kg |
| Max. allowed weight | 1735 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 47 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Engine number | B634I933 |