



report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER TDV8 VOGUE SE
Colour	Blue
Year of manufacture	2011
Top speed	130 mph
0 - 100 km/h	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	230 kW / 313 HP / 313 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	4.367 cc
Cylinders	8
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	34.5 mpg
Consumption combined	30.1 mpg
CO2 emission	253 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-06-19
Pictures	22
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-12
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	20
Total items failed	0

MOT #10	2023-06-13 12:40
---------	------------------

MOT test number	715257607637
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-06-12
------------------	------------

- Advice** Brake pipe corroded, covered in grease or other material Front to Rear Pipes Under Sill (1.1.11 (c))
- Advice** Rear Shock absorbers has light misting of oil N/S and O/S (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened N/S and O/S (1.1.14 (a) (ii))
- Advice** Rear Sub-frame pin or bush worn but not resulting in excessive movement N/S and O/S (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened N/S and O/S (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #9** 2022-05-09 11:32**MOT test number** 921386166271**Result** ✓ Passed**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer bush on hub (5.3.4 (a) (i))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge very low (5.2.3 (e))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #8** 2021-06-01 15:02**MOT test number** 899096038831**Result** ✓ Passed**MOT #7** 2020-11-10 11:28**MOT test number** 959924015426**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #6** 2019-07-22 09:48**MOT test number** 235809491401**Result** ✓ Passed

**MOT #5** 2018-06-18 12:23**MOT test number** 929650624593**Result** ✓ Passed**MOT #4** 2017-06-19 15:01**MOT test number** 538527284158**Result** ✓ Passed**MOT #3** 2017-03-20 09:37**MOT test number** 168899412358**Result** ✓ Passed**MOT #2** 2015-09-09 09:33**MOT test number** 413114459415**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Chassis/VIN plate missing**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #1** 2014-09-08 12:23**MOT test number** 938801954258**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
12 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	12 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-28
Current registration	*****
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-09-21
Last registration	2023-06-13
Complete history	See info



Registration #1	2011-09-21	17 mi
Registration #2	2014-09-08	38.554 mi
Registration #3	2015-09-09	55.507 mi
Registration #4	2017-03-20	85.996 mi
Registration #5	2017-06-19	90.876 mi
Registration #6	2018-06-18	98.117 mi
Registration #7	2019-06-20	101.277 mi
Registration #8	2019-06-20	101.277 mi
Registration #9	2019-06-20	101.277 mi
Registration #10	2019-06-20	101.277 mi
Registration #11	2019-06-20	101.277 mi
Registration #12	2019-06-20	101.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2216 mm
Height	1865 mm
Length	4967 mm
Wheel base	2880 mm
Kerb weight	2710 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0006899448DT