





report date: 2024-03-29

### General information

Make	PEUGEOT
Model	3008 THP S/S ALLURE
Colour	Blue
Year of manufacture	2017
Top speed	128 mph
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	165 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

### Internet history


#### Entry 2

Date 2022-07-12

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date 2021-05-26

Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-05-31
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	3
Total items failed	3

MOT #5	2023-05-31 16:02
MOT test number	172570827096
Result	<b>✓</b> Passed
Next expiry date	2024-05-31

MOT #4	2022-05-27 09:26
MOT test number	386482757945
Result	<b>√</b> Passed

MOT #3	2021-06-01 09:46
MOT test number	684436635715
Result	<b>✓</b> Passed

MOT #2 2020-09-23 1	2:08
---------------------	------

**MOT test number** 892495792955

Result \(\sqrt{Passed}\)

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded on outer surface (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2020-09-22 13:18

**MOT test number** 679324647600

#### Result

**X** Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded on outer surface (1.1.14 (a) (ii))

Fail Offside Rear Seat belt not functioning as intended not retracting as intended (7.1.2 (c))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** 

Nearside Rear Nail in tyre

CarCheck.co.uk page 4/11



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	31 May 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

_	
Owner	hictory
OWITEL	HIISLULV

For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***********	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	OK OK
Plate since	
Current registration	UK ZIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-11-10
Last registration	2023-05-31
Complete history	See info



Registration #1	2017-11-10	24 mi
Registration #2	2020-09-22	24.108 mi
Registration #3	2020-09-23	24.111 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

	•	•	 •	•	
S0225					Air conditioning
S0295					
S0482					
S0501					

\$0501 \$0566

The PEUGEOT factory car options list is only available in the premium report.

\$0567 \$0569

View the complete PEUGEOT factory list for this vehicle <u>here</u>.

More info >

### Safety ratings

NCAP rating	****
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



## Dimensions & weight

Width	1841 mm
Height	1624 mm
Length	4447 mm
Wheel base	2675 mm
Kerb weight	1300 kg
Max. allowed weight	1950 kg

## Additional information

Fuel tank capacity	53 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

**Engine number** FJCC2339437