



report date: 2025-01-14

General information

Make	MINI
Model	COUNTRYMAN COOPER SD COOPER SD
Colour	White
Year of manufacture	2012
Top speed	123 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-09-01
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-09-06
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	9
Total items failed	6

<b>MOT #12</b>	2024-09-05 15:46
MOT test number	379752607767
Result	✓ Passed
Next expiry date	2025-09-06

<b>MOT #11</b>	2023-08-22 11:38
MOT test number	565227746938
Result	✓ Passed

<b>MOT #10</b>	2022-08-19 11:18
MOT test number	450965685554
Result	✓ Passed
<b>Advice</b>	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
<b>Minor</b>	Windscreen wiper blade defective Both slightly smearing (3.4 (b) (i))

<b>MOT #9</b>	2021-09-07 14:34
MOT test number	109538160683
Result	✓ Passed

<b>MOT #8</b>	2020-11-28 12:30
MOT test number	751529029910
Result	✓ Passed



<b>MOT #7</b>	2019-05-31 15:11
<b>MOT test number</b>	373934105793
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2019-05-30 15:17
<b>MOT test number</b>	730912156480
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
<b>Fail</b>	Nearside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
<b>Fail</b>	Offside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

<b>MOT #5</b>	2018-08-09 09:31
<b>MOT test number</b>	800345486381
<b>Result</b>	✓ Passed
<b>Advice</b>	No emissions detected at time of test

<b>MOT #4</b>	2017-08-03 10:58
<b>MOT test number</b>	167563579078
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #3</b>	2016-08-08 15:18
<b>MOT test number</b>	128262514975
<b>Result</b>	✓ Passed



**MOT #2** 2016-08-08 09:00

**MOT test number** 588149303142

**Result** ✗ Failed

**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)

**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)

**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure inner edge worn close but not showing cords (4.1.D.1b)

**MOT #1** 2015-08-11 10:56

**MOT test number** 589293225227

**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 September 2025

✓  
**MOT**

**Expires:**  
6 September 2025

**Tax status** Valid until 1 September

**Days left** 199

**MOT expiry date** 6 September 2025

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	NV12XEA
Plate since	2019-09-29
Current registration	NV12XEA
Plate since	2019-09-29

More info >



**Finance check**

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



## Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	14
<b>First mileage registration</b>	2012-08-13
<b>Last registration</b>	2024-09-05
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2012-08-13	17 mi
<b>Registration #2</b>	2015-08-11	23.980 mi
<b>Registration #3</b>	2016-08-08	31.566 mi
<b>Registration #4</b>	2016-08-08	31.566 mi
<b>Registration #5</b>	2017-08-03	40.498 mi
<b>Registration #6</b>	2018-08-09	52.414 mi
<b>Registration #7</b>	2019-05-30	61.598 mi
<b>Registration #8</b>	2020-05-29	61.598 mi
<b>Registration #9</b>	2020-05-29	61.598 mi
<b>Registration #10</b>	2020-05-29	61.598 mi
<b>Registration #11</b>	2020-05-29	61.598 mi
<b>Registration #12</b>	2020-05-29	61.598 mi
<b>Registration #13</b>	2020-05-29	61.598 mi
<b>Registration #14</b>	2024-09-05	61.598 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	72068241