



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN GT TDI DSG DPF 140
Colour	Blue
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-09
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-09
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	25
Total items failed	3

MOT #16	2023-07-06 11:18
MOT test number	192287464393
Result	✓ Passed
Next expiry date	2024-07-09
Advice	Front Tyre slightly damaged/cracking or perishing n/s & o/s (5.2.3 (d) (ii))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement n/s & o/s both bushes attached to subframe (5.3.4 (a) (i))
Advice	Rear Shock absorbers has light misting of oil n/s & o/s (5.3.2 (b))

MOT #15	2023-07-06 11:18
MOT test number	817984177080
Result	✗ Failed
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement n/s & o/s both bushes attached to subframe (5.3.4 (a) (i))
Pass with rectification	Offside Front Headlamp are incorrectly positioned (4.1.4 (a))
Advice	Front Tyre slightly damaged/cracking or perishing n/s & o/s (5.2.3 (d) (ii))
Advice	Rear Shock absorbers has light misting of oil n/s & o/s (5.3.2 (b))

MOT #14	2022-07-07 15:31
MOT test number	932875027032
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13** 2021-07-10 09:50**MOT test number** 674760483786**Result** ✓ Passed**MOT #12** 2020-10-02 13:18**MOT test number** 746023379933**Result** ✓ Passed**MOT #11** 2020-10-02 13:18**MOT test number** 908649992107**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #10** 2019-09-24 09:14**MOT test number** 406557088311**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-09-15 08:12**MOT test number** 846374037699**Result** ✓ Passed**Advice** Offside Rear Service brake binding but not excessively Recommend repair (1.2.1 (f))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #8** 2017-10-07 11:47**MOT test number** 332863143128**Result** ✓ Passed

**MOT #7** 2017-10-07 11:12**MOT test number** 209163912524**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #6** 2016-08-17 15:52**MOT test number** 761454661835**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Child Seat fitted not allowing full inspection of adult belt X2**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-08-05 12:49**MOT test number** 459737615227**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2014-07-09 16:42**MOT test number** 689610794181**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Rear nearside offside shock absorber bump stops perished and split



MOT #3	2013-07-17 17:39
MOT test number	265038293118
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	The nearside rear shockabsorber bump stop is perished and detached
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	The offside rear shockabsorber is becoming perished

MOT #2	2012-07-04 14:50
MOT test number	167516382168
Result	✓ Passed
Notice	Rear nearside offside shock absorber bump stops deteriorated

MOT #1	2011-07-04 09:22
MOT test number	906555081177
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
9 July 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	9 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 MM08YBD
Plate since	2024-03-29
Current registration	 MM08YBD
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-07-28
Last registration	2023-07-06
Complete history	See info



Registration #1	2008-07-28	25 mi
Registration #2	2011-07-04	31.505 mi
Registration #3	2012-07-04	42.089 mi
Registration #4	2013-07-17	52.414 mi
Registration #5	2014-07-09	60.384 mi
Registration #6	2015-08-05	69.614 mi
Registration #7	2016-08-17	78.645 mi
Registration #8	2017-10-07	85.909 mi
Registration #9	2017-10-07	85.909 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1486 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	BKD C39550