

Ford



General information

Make	FORD
Model	RANGER WILDTRAK 4X4 DCB TDCI
Colour	White
Year of manufacture	2017
Top speed	109 mph
0 - 100 km/h	10.3 seconds
0 - 60 mph	10.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	147 kW / 200 HP / 198 BHP
Max. torque	470 Nm at 2.750 rpm
Engine capacity	3.198 cc
Cylinders	5
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	228 g/km
CO2 label	L







Internet history

Entry 3	
Date	2023-12-08
Pictures	50
Listing price	View report



source: cargurus.co.uk

Entry 2	
Date	2023-08-24
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2021-12-02
Pictures	13
Listing price	View report



source: cargurus.co.uk



Video viewing

Book ;



MOT history

MOT expiry date	2024-12-18
MOT pass rate	50 %
MOT passed	4
Failed MOT tests	4
Total advice items	2
Total items failed	7

MOT #8	2023-12-19 09:58
MOT test number	429583895036
Result	✓ Passed
Next expiry date	2024-12-18

MOT #7	2023-12-13 12:31
MOT test number	167448038263
Result	🗙 Failed
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
Fail Driver's door cannot be opened from inside the vehicle (6.2.3 (a))	
Fail Oil leaking excessively from engine (8.4.1 (a) (i))	

МОТ #6	2023-09-20 15:01
MOT test number	594052036934
Result	× Failed
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Oil leaking excessively from engine (8.4.1 (a) (i))	
Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	





MOT #5	2022-10-28 07:51
MOT test number	367829002935
Result	✓ Passed
MOT #4	2022-10-25 15:14
MOT test number	670237061585
Result	🗙 Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
MOT #3	2021-10-27 11:48
MOT test number	384131559999
Result	✓ Passed
MOT #2	2020-10-12 10:46
MOT test number	597101021299
Result	✓ Passed
MOT #1	2020-10-09 12:47
MOT test number	660472841842
Result	🗙 Failed
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Outer side wall (5.2.3 (d) (i))	





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-10-30
Last registration	2023-12-19
Complete history	See info



Registration #1	2017-10-30	20 mi
Registration #2	2020-10-09	23.703 mi
Registration #3	2020-10-12	23.769 mi
Registration #4	2021-10-27	29.702 mi
Registration #5		11.777 mi
Registration #6	2022-10-25	37.795 mi
Registration #7		11.777 esi
Registration #7 Registration #8		11.222 est
		01.000 est 01.000 est 01.000 est
Registration #8		01,000 est 01,000 est 01,000 est 01,000 est
Registration #8 Registration #9		01,000 44 01,000 44 01,000 44 01,000 44 01,000 44





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	86%
Pedestrian	81%
Safety systems	71%
Overall rating	89%
Video	see crash video



Dimensions & weight	
Width	2163 mm
Height	1815 mm
Length	5362 mm
Wheel base	3 mm
Kerb weight	2083 kg
Max. allowed weight	3200 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of axles CarCheck.co.uk	2 page 10/10