



MJIIFY

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI
Colour	Red
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg





Internet history

Entry 1

Date	2021-08-09
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-08
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #11	2023-06-07 13:49
MOT test number	787166286805
Result	✓ Passed
Next expiry date	2024-06-08
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing tyre outer sidewall damaged (5.2.3 (d) (ii))

MOT #10	2023-06-07 08:01
MOT test number	477908579527
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing tyre outer sidewall damaged (5.2.3 (d) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Anti-roll bar pin or bush worn but not resulting in excessive movement rear anti-roll bar, both centre mounting 'D' bushes (5.3.4 (a) (i))

MOT #9	2022-06-06 10:53
MOT test number	573758397796
Result	✓ Passed

**MOT #8** 2021-06-09 08:27**MOT test number** 441231639148**Result** ✓ Passed**Advice** Central Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Central Front Windscreen wiper blade defective smearing (3.4 (b) (i))**Advice** Central Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2020-07-20 14:00**MOT test number** 241599010416**Result** ✓ Passed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MOT #6** 2019-07-16 09:57**MOT test number** 266179990216**Result** ✓ Passed**MOT #5** 2018-07-24 07:57**MOT test number** 387921903329**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened from standing (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened from standing (1.1.14 (a) (ii))**MOT #4** 2017-05-30 08:13**MOT test number** 139522497428**Result** ✓ Passed



MOT #3	2016-06-23 11:28
MOT test number	543339479360
Result	✓ Passed
MOT #2	2015-06-04 16:21
MOT test number	927615255149
Result	✓ Passed
MOT #1	2014-06-20 11:35
MOT test number	107731474129
Result	✓ Passed
Advice	Rear registration plate delaminated but not likely to be misread (6.3.1d)
Notice	N/S/R tyre cracking on the outer wall and worn on outsides of tread



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
8 June 2024

Tax status	Valid until 1 November
------------	------------------------

Days left	186
-----------	-----

MOT expiry date	8 June 2024
-----------------	-------------

Full MOT history	See MOT history
------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-06-27
Last registration	2023-06-07
Complete history	See info



Registration #1	2011-06-27	20 mi
Registration #2	2014-06-20	59.888 mi
Registration #3	2015-06-04	73.284 mi
Registration #4	2016-06-23	84.609 mi
Registration #5	2017-05-30	86.286 mi
Registration #6	2018-07-24	88.026 mi
Registration #7	2019-07-16	88.479 mi
Registration #8	2019-06-20	88.479 mi
Registration #9	2019-06-20	88.479 mi
Registration #10	2019-06-20	88.479 mi
Registration #11	2019-06-20	88.479 mi
Registration #12	2019-06-20	88.479 mi
Registration #13	2019-06-20	88.479 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Kerb weight	1490 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	CFH 169027