



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Grey
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-24
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-02-05
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	19
Total items failed	8

## MOT #152024-02-05 13:02

MOT test number632008979341

Result✓ Passed

Next expiry date2025-02-05

**Advice** Items removed from driver's view prior to test**Advice** Offside Rear Nail in tyre**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

## MOT #142024-02-05 10:06

MOT test number673827743825

Result✗ Failed

**Advice** Items removed from driver's view prior to test**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Nail in tyre

## MOT #132023-02-06 14:00

MOT test number208991541513

Result✓ Passed

**MOT #12** 2021-11-23 12:14**MOT test number** 197124524722**Result** ✓ Passed**MOT #11** 2021-02-05 11:34**MOT test number** 389119274200**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking or perishing on outer sidewall (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**MOT #10** 2021-02-05 11:34**MOT test number** 385646959933**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking or perishing on outer sidewall (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**MOT #9** 2020-02-03 13:38**MOT test number** 484480552185**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2020-02-03 12:40**MOT test number** 725139303867**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2019-02-06 09:44**MOT test number** 961932906708**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2019-02-01 12:08**MOT test number** 344926502715**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Fail** Nearside Rear Hydraulic brake calliper insecurely mounted and braking performance affected (1.1.16 (c) (ii))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #5** 2018-01-29 11:13**MOT test number** 910872931361**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2017-02-07 11:47**MOT test number** 621707447860**Result** ✓ Passed



MOT #3	2017-02-07 09:14
MOT test number	577648769432
Result	✗ Failed
Fail	Offside Front Headlamp aim too low (1.8)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2015-12-23 12:01
MOT test number	897982428296
Result	✓ Passed

MOT #1	2015-12-23 12:01
MOT test number	514351446216
Result	✗ Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
5 February 2025

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	5 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>KV06DAV</b>
Plate since	2024-03-29
Current registration	 <b>KV06DAV</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-01-19
Last registration	2024-02-05
Complete history	<a href="#">See info</a>



Registration #1	2013-01-19	6 mi
Registration #2	2015-12-23	38.635 mi
Registration #3	2015-12-23	38.635 mi
Registration #4	2017-02-07	39.457 mi
Registration #5	2017-02-07	39.457 mi
Registration #6	2018-01-29	46.528 mi
Registration #7	2019-02-01	55.266 mi
Registration #8	2019-02-06	55.376 mi
Registration #9	2020-02-03	61.666 mi
Registration #10	2020-02-03	61.666 mi
Registration #11	2020-02-03	61.666 mi
Registration #12	2020-02-03	61.666 mi
Registration #13	2020-02-03	61.666 mi
Registration #14	2020-02-03	61.666 mi
Registration #15	2020-02-03	61.666 mi
Registration #16	2020-02-03	61.666 mi
Registration #17	2020-02-03	61.666 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ