



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D2 R-DESIGN
Colour	Red
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-04-08
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-03
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	16
Total items failed	3

MOT #11	2024-03-23 10:35
MOT test number	153130097067
Result	✓ Passed
Next expiry date	2025-04-03

MOT #10	2023-03-13 11:59
MOT test number	830443539746
Result	✓ Passed
Advice	Rear Coil spring corroded Both nearside and offside (5.3.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Nail in tyre
Advice	Nearside Front Nail in tyre

MOT #9	2022-04-04 14:20
MOT test number	474610299730
Result	✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8** 2022-03-29 16:37**MOT test number** 991395780807**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Pass with rectification** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #7** 2021-06-02 10:15**MOT test number** 658630895749**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2020-05-21 11:19**MOT test number** 179392575497**Result** ✓ Passed**MOT #5** 2019-06-05 10:41**MOT test number** 452232214597**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #4	2018-06-11 15:36
---------------	------------------

MOT test number	185289489040
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2017-11-14 16:10
---------------	------------------

MOT test number	902965090329
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2016-09-20 12:57
---------------	------------------

MOT test number	975345722354
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

MOT #1	2015-09-22 15:51
---------------	------------------

MOT test number	385129941523
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
3 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	3 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AF62YXE
Plate since	2019-03-29
Current registration	AF62YXE
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-09-21
Last registration	2024-03-23
Complete history	See info



Registration #1	2012-09-21	22 mi
Registration #2	2015-09-22	46.397 mi
Registration #3	2016-09-20	56.595 mi
Registration #4	2017-11-14	68.244 mi
Registration #5	2018-06-11	72.941 mi
Registration #6	2019-06-05	78.703 mi
Registration #7	2020-05-21	84.642 mi
Registration #8	2021-05-20	91.577 mi
Registration #9	2022-05-20	98.512 mi
Registration #10	2023-05-20	105.447 mi
Registration #11	2024-03-23	112.382 mi
Registration #12		
Registration #13		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	2259719