



OVIIJXU


report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS SE TSI
Colour	Silver
Year of manufacture	2011
Top speed	135 mph
0 - 100 km/h	8.8 seconds
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 kW / 161 HP / 158 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-08
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	9
Total items failed	7

MOT #13 2024-02-06 16:02

MOT test number 634252987693

Result ✓ Passed

Next expiry date 2025-02-08

Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Windscreen wiper blade defective (3.4 (b) (i))

MOT #12 2023-02-08 11:42

MOT test number 328632371241

Result ✓ Passed

MOT #11 2023-02-06 10:49

MOT test number 980466019610

Result ✗ Failed

Fail Offside Front Driver's door cannot be opened from inside the vehicle (6.2.3 (a))

Fail Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #10** 2022-02-05 18:40**MOT test number** 225444158236**Result** ✓ Passed**MOT #9** 2021-02-09 16:54**MOT test number** 744090353610**Result** ✓ Passed**MOT #8** 2019-04-01 16:03**MOT test number** 668238895564**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge cuts and cracks on centre treads (5.2.3 (e))

Advice Offside Rear tyre unevenly worn on inner edges, and has cracks on centre and outer sidewall.

Advice Offside Front Tyre worn close to legal limit/worn on edge cuts and cracks on outer sidewall. (5.2.3 (e))

MOT #7 2019-03-29 15:26**MOT test number** 284008526852**Result** ✗ Failed

Advice Offside Rear tyre unevenly worn on inner edges, and has cracks on centre and outer sidewall.

Advice Nearside Front Tyre worn close to legal limit/worn on edge cuts and cracks on centre treads (5.2.3 (e))

Fail Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge cuts and cracks on outer sidewall. (5.2.3 (e))

MOT #6 2018-03-23 10:06**MOT test number** 284152108351**Result** ✓ Passed

Advice Nearside Rear Nail in tyre outer edges has a screw .



MOT #5	2017-03-13 10:49
---------------	------------------

MOT test number	862588139620
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2016-03-18 10:36
---------------	------------------

MOT test number	278597053787
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2015-03-13 10:54
---------------	------------------

MOT test number	988432375043
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2014-03-28 15:29
---------------	------------------

MOT test number	379857084078
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2014-03-28 12:09
---------------	------------------

MOT test number	238707984008
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	---

Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	--



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 OV11JXU
Plate since	2019-03-29
Current registration	 OV11JXU
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-31
Last registration	2024-02-06
Complete history	See info



Registration #1	2011-03-31	6 mi
Registration #2	2014-03-28	25.195 mi
Registration #3	2014-03-28	25.195 mi
Registration #4	2015-03-13	36.670 mi
Registration #5	2016-03-18	49.367 mi
Registration #6	2017-03-13	54.251 mi
Registration #7	2018-03-23	63.911 mi
Registration #8	2019-03-29	70.237 mi
Registration #9	2020-03-29	70.237 mi
Registration #10	2021-03-29	70.237 mi
Registration #11	2022-03-29	70.237 mi
Registration #12	2023-03-29	70.237 mi
Registration #13	2024-03-29	70.237 mi
Registration #14	2025-03-29	70.237 mi
Registration #15	2026-03-29	70.237 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2009 mm
Height	1444 mm
Length	4423 mm
Wheel base	2578 mm
Kerb weight	1505 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles

2

Engine number

CAV 261545