



PEUGEOT



report date: 2024-03-28

General information

| | |
|---------------------|-----------------------|
| Make | PEUGEOT |
| Model | 307 S COUPE CABRIOLET |
| Colour | Grey |
| Year of manufacture | - |
| Top speed | 128 mph |
| 0 - 60 mph | 11.3 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 138 BHP |
| Max. torque | 200 Nm at 4.000 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 23.2 mpg |
| Consumption extra urban | 44.8 mpg |
| Consumption combined | 33.6 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-27 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

**MOT history**

| | |
|-------------------------|---|
| MOT #17 | 2021-09-15 12:46 |
| MOT test number | 823541620911 |
| Result | ✓ Passed |
| Next expiry date | 2022-09-14 |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|------------------------|--|
| MOT #16 | 2020-12-30 14:32 |
| MOT test number | 564384722052 |
| Result | ✓ Passed |
| Minor | Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |

| | |
|------------------------|--|
| MOT #15 | 2019-12-02 10:23 |
| MOT test number | 767143568739 |
| Result | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Exhaust has a minor leak of exhaust gases (6.1.2 (a)) |

| | |
|------------------------|------------------|
| MOT #14 | 2018-12-04 10:30 |
| MOT test number | 476585823105 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #13 | 2018-01-02 15:17 |
| MOT test number | 197571659846 |
| Result | ✓ Passed |

**MOT #12** 2016-11-30 16:39**MOT test number** 410190556995**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened scored (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened scored (3.5.1i)**MOT #11** 2016-11-30 12:54**MOT test number** 878997550323**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened scored (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened scored (3.5.1i)**Fail** Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.2.C.1c)**MOT #10** 2015-11-27 17:13**MOT test number** 258599645535**Result** ✓ Passed**MOT #9** 2014-11-13 17:17**MOT test number** 977997014377**Result** ✓ Passed**MOT #8** 2014-05-21 09:23**MOT test number** 479171044139**Result** ✓ Passed**MOT #7** 2014-05-21 09:23**MOT test number** 208591744178**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)

**MOT #6** 2013-05-15 11:10**MOT test number** 588575833190**Result** ✓ Passed**Advice** Offside Inner Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Inner Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2012-05-09 15:49**MOT test number** 247450332419**Result** ✓ Passed**MOT #4** 2011-06-01 14:56**MOT test number** 648842951166**Result** ✓ Passed**MOT #3** 2011-05-31 16:25**MOT test number** 856421951137**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Nail in offside front tyre**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Nail in nearside rear tyre



| | |
|-----------------|----------------------------|
| MOT #2 | 2009-11-18 10:39 |
| MOT test number | 581252629325 |
| Result | ✓ Passed |
| Notice | Nail in nearside rear tyre |
| Notice | Nail in offside front tyre |

| | |
|-------------------------|---|
| MOT #1 | 2009-11-18 10:39 |
| MOT test number | 731362329394 |
| Result | ✗ Failed |
| Notice | Nail in nearside rear tyre |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Notice | Nail in offside front tyre |
| Pass with rectification | Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | BG56RAX |
| Plate since | 2024-03-28 |
| Current registration | BG56RAX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2006-11-30 |
| Last registration | 2021-09-15 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-11-30 | 12 mi |
| Registration #2 | 2009-11-18 | 15.113 mi |
| Registration #3 | 2011-05-31 | 17.305 mi |
| Registration #4 | 2011-06-01 | 17.305 mi |
| Registration #5 | 2012-05-09 | 17.900 mi |
| Registration #6 | 2013-05-15 | 19.829 mi |
| Registration #7 | 2014-05-21 | 22.224 mi |
| Registration #8 | 2014-11-13 | 23.239 mi |
| Registration #9 | 2015-11-27 | 25.064 mi |
| Registration #10 | 2016-05-20 | 25.277 mi |
| Registration #11 | 2016-05-20 | 25.277 mi |
| Registration #12 | 2016-05-20 | 25.277 mi |
| Registration #13 | 2016-05-20 | 25.277 mi |
| Registration #14 | 2016-05-20 | 25.277 mi |
| Registration #15 | 2016-05-20 | 25.277 mi |
| Registration #16 | 2016-05-20 | 25.277 mi |
| Registration #17 | 2016-05-20 | 25.277 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1757 mm |
| Height | 1440 mm |
| Length | 4357 mm |
| Wheel base | 2605 mm |
| Kerb weight | 1573 kg |
| Max. allowed weight | 1900 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 4 |

| | |
|------------------------|-------------|
| Number of axles | 2 |
| Engine number | LH4R1405241 |