




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Grey
Year of manufacture	2007
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-25
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-06
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	40
Total items failed	17

MOT #20	2023-12-07 14:14
MOT test number	423708907095
Result	✓ Passed
Next expiry date	2024-12-06
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19	2023-12-07 11:16
MOT test number	340161326815
Result	✗ Failed
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Windscreen washer not working (3.5 (a))



MOT #18 2022-12-05 11:19

MOT test number 227243353960

Result ✓ Passed

- Advice** HANDBRAKE LEVER HIGH
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** EXHAUST BACKBOX CORRODED
- Advice** O/S/F AND N/S/F HEADLAMP LENSES IN POOR CONDITION
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17 2022-12-05 11:19

MOT test number 453830954418

Result ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** HANDBRAKE LEVER HIGH
- Advice** EXHAUST BACKBOX CORRODED
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** O/S/F AND N/S/F HEADLAMP LENSES IN POOR CONDITION

MOT #16 2021-09-25 13:18

MOT test number 393074888891

Result ✓ Passed

- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15 2020-10-09 16:10

MOT test number 275802168759

Result ✓ Passed



MOT #14	2020-10-05 16:21
MOT test number	131065959467
Result	✗ Failed
Advice	Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
Fail	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #13	2019-09-24 14:15
MOT test number	368023384944
Result	✓ Passed
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))



MOT #12 2019-09-12 15:28

MOT test number 816965220908

Result ✗ Failed

- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #11 2018-07-19 09:58

MOT test number 501224683016

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #10 2018-07-18 16:05

MOT test number 186628152470

Result ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #9 2017-07-10 10:04

MOT test number 722383411755

Result ✓ Passed

- Advice** Both front tyres wearing unevenly.
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #8 2016-07-14 13:43

MOT test number 115488787452

Result ✓ Passed

- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #7 2015-07-02 10:11

MOT test number 149003185120

Result ✓ Passed

- Notice** Nearside rear tyre cracked
- Notice** Nail in offside rear tyre



MOT #6 2014-07-04 12:04

MOT test number 438815284124

Result ✓ Passed

- Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5 2014-07-04 12:04

MOT test number 456965184110

Result ✗ Failed

- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #4 2013-06-05 17:22

MOT test number 296616953106

Result ✓ Passed

MOT #3 2012-05-08 15:15

MOT test number 867229622136

Result ✓ Passed

MOT #2 2011-05-03 11:56

MOT test number 399593221168

Result ✓ Passed



MOT #1	2010-04-29 10:05
MOT test number	820779610187
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 December 2024

✓
MOT

Expires:
6 December 2024

Tax status Valid until 1 December

Days left 215

MOT expiry date 6 December 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	PL07CNJ
Plate since	2019-03-29
Current registration	PL07CNJ
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-06-29
Last registration	2023-12-07
Complete history	See info



Registration #1	2007-06-29	10 mi
Registration #2	2010-04-29	5.299 mi
Registration #3	2011-05-03	8.742 mi
Registration #4	2012-05-08	12.589 mi
Registration #5	2013-06-05	16.100 mi
Registration #6	2014-07-04	23.981 mi
Registration #7	2015-07-02	34.026 mi
Registration #8	2016-07-14	41.161 mi
Registration #9	2017-07-10	44.115 mi
Registration #10	2018-07-18	46.351 mi
Registration #11	2018-07-19	46.351 mi
Registration #12	2019-06-20	51.277 mi
Registration #13	2019-06-20	51.277 mi
Registration #14	2019-06-20	51.277 mi
Registration #15	2019-06-20	51.277 mi
Registration #16	2019-06-20	51.277 mi
Registration #17	2019-06-20	51.277 mi
Registration #18	2019-06-20	51.277 mi
Registration #19	2019-06-20	51.277 mi
Registration #20	2019-06-20	51.277 mi
Registration #21	2019-06-20	51.277 mi

[More info >](#)



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 313622