





report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO SOUND
Colour	Grey
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2022-07-27

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-26
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	20
Total items failed	2

MOT #14	2023-07-25 09:50
MOT test number	190508890062
Result	✓ Passed
Next expiry date	2024-07-26
Advice Nearside Rear Nail in tyre	

MOT #13	2022-07-27 15:20
MOT test number	288960408120
Result	✓ Passed

MOT #12		2022-07-26 14:47
MOT test	number	461182016171
Result		X Failed
MAJOR	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
MAJOR	Front Lower Emissions not tested Exhaust excessive leak (8.2.1.2 (d))	
MAJOR	Front Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
MAJOR	Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #11		2021-11-10 11:17
MOT test	number	726802903177
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10		2020-11-10 12:39
MOT test number		340624856420
Result		✓ Passed
MOT #9		2020-11-10 12:39
MOT test number		445016465122
Result		× Failed
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #8	2019-10-18 14:46
MOT test number	524101850215
Result	✓ Passed

MOT #7		2018-10-31 11:51
MOT test	number	505106011975
Result		✓ Passed
Advice	Offside Front Tyre has slight cracks in tread	
Advice	Offside Rear Tyre has slight cracks in tread	
Advice	Nearside Front Tyre has slight cracks in tread	
Advice	Nearside Rear Tyre has slight cracks in tread	
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Exhaust back box corroded and has slight leak	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Advice Exhaust Back Box Corroded

Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)

MOT test number

Result

Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Exhaust Back Box Corroded

 MOT #4
 2016-11-18 17:41

 MOT test number
 876059779738

 Result
 ✓ Passed

 MOT #3
 2015-12-23 09:55

 MOT test number
 740518600090

 Result
 ✓ Passed

 Advice
 Child seat

MOT #2

MOT test number

Result

Notice Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1

MOT test number

488118743387

Result

Notice Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

$\overline{}$	1415	- r	ᄂ	C+	0 10
U	wr	ıer	m	เรเ	or۷

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	ZIS UK
Plate since	
Current registration	UK NA
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-12-24
Last registration	2023-07-25
Complete history	See info



Registration #1	2010-12-24	20 mi
Registration #2	2013-12-14	22.869 mi
Registration #3	2014-12-13	28.817 mi
Registration #4	2015-12-23	33.031 mi
Registration #5	2016-11-18	34.808 mi
Registration #6	2017-11-18	37.548 mi
Registration #7	2017-11-18	37.548 mi
Registration #8	2018-10-31	40.084 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		10.700 au
_		

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13