





### General information

Make	NISSAN
Model	QASHQAI DCI TEKNA
Colour	Blue
Year of manufacture	2018
Top speed	113 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	108 BHP
Max. torque	260 Nm at 2.500 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	А





CAZOO The better way to buy your next on

-

## Internet history

Date

Pictures

Listing price

2021-10-16 29

View report

CAZOO The better way to buy your

CAZOO The better way to buy your next car



source: yesauto.com





## MOT history

MOT expiry date	2024-10-11
MOT pass rate	100 %
MOT passed	3
Failed MOT tests	0
Total advice items	6
Total items failed	0

MOT #3	2023-10-06 11:36
MOT test number	187643593376
Result	Passed
Next expiry date         2024-10-11	
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply	v or cords (5.2.3 (d) (i))

MOT test number       493873155135         Result       Passed         Advice       Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm front bush deteriorated (5.3.4 (a) (i))         Minor       Front Suspension arm ball joint dust cover severely deteriorated both lower arm ball joint dust covers deteriorated (5.3.4 (b) (i))         Advice       Items removed from driver's view prior to test holder on windscreen and air freshener from rear
<ul> <li>Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm front bush deteriorated (5.3.4 (a) (i))</li> <li>Minor Front Suspension arm ball joint dust cover severely deteriorated both lower arm ball joint dust covers deteriorated (5.3.4 (b) (i))</li> </ul>
arm front bush deteriorated (5.3.4 (a) (i))  Minor Front Suspension arm ball joint dust cover severely deteriorated both lower arm ball joint dust covers deteriorated (5.3.4 (b) (i))
covers deteriorated (5.3.4 (b) (i))
Advice Items removed from driver's view prior to test holder on windscreen and air freshener from rear
view mirror
Minor       Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))         Advice       Emissions too clean to register

MOT #1	2021-10-12 09:23
MOT test number	805807731638
Result	✓ Passed



Tax & MOT check

✓ Taxed	√ MOT
Tax due: 1 December 2024	Expires: 11 October 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	11 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	



#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >





## Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2018-09-25
Last registration	2023-10-06
Complete history	<u>See info</u>



Registration #1	2018-09-25	27 mi
Registration #2	2021-10-12	36.525 mi
Registration #3		11.777 esi
Registration #4		11.777 est
Registration #5		11.777 mi

More info >





## Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	88%
Children	83%
Pedestrian	69%
Safety systems	79%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1806 mm
Height	1590 mm
Length	4394 mm
Wheel base	2646 mm
Kerb weight	1379 kg
Max. allowed weight	1910 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/10

Number of axles	2
Engine number	D643562