



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	ESPACE RUSH DCI (120BHP)
Colour	Silver
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	270 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	40.4 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #17</b>	2021-08-18 12:56
<b>MOT test number</b>	274772971194
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-08-17
<b>Minor</b>	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
<b>Advice</b>	Passenger seat(s) missing at time of test
<b>Advice</b>	Tyre worn close to legal limit/worn on edge both fronts (5.2.3 (e))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Nearside Rear brake pads excessively worn more than offside rear
<b>Advice</b>	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

<b>MOT #16</b>	2020-08-18 09:05
<b>MOT test number</b>	587396145558
<b>Result</b>	✓ Passed
<b>Advice</b>	Play in steering rack inner joint(s)
<b>Advice</b>	Brake disc worn, pitted or scored, but not seriously weakened front and rear rusty (1.1.14 (a) (ii))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #15</b>	2019-03-18 16:52
<b>MOT test number</b>	430141249132
<b>Result</b>	✓ Passed
<b>Advice</b>	Play in steering rack inner joint(s)
<b>Minor</b>	Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #14** 2018-03-19 14:47**MOT test number** 172381385343**Result** ✓ Passed**Advice** O/s front jacking point damaged**Advice** Oil leak**Advice** Nearside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Rear brake binding slightly**Advice** Play in steering rack inner joint(s) both**MOT #13** 2018-03-16 13:08**MOT test number** 350337019148**Result** ✗ Failed**Advice** O/s front jacking point damaged**Advice** Play in steering rack inner joint(s) both**Advice** Nearside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Oil leak**Advice** Nearside Rear brake binding slightly**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #12** 2017-02-14 15:03**MOT test number** 467391484057**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2015-05-15 13:28**MOT test number** 387765435103**Result** ✓ Passed**Notice** Engine oil on minimum**MOT #10** 2015-05-14 12:19**MOT test number** 857804135180**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Engine oil on minimum**MOT #9** 2014-04-03 17:14**MOT test number** 115733994482**Result** ✓ Passed**Notice** Child seat n/s/r**Notice** Service reminder on**Notice** O/s/f tyre worn low both edges**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8**

2014-04-03 10:11

**MOT test number**

105333394463

**Result****✗ Failed**

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Service reminder on
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Notice** O/s/f tyre worn low both edges
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Notice** Child seat n/s/r
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #7**

2013-04-29 11:52

**MOT test number**

877729713139

**Result****✓ Passed**

- Notice** Child seats fitted to L.H,center&R.H, rear seats
- Notice** R.H. park brake could be improved

**MOT #6**

2013-04-29 09:59

**MOT test number**

767089413124

**Result****✗ Failed**

- Notice** Child seats fitted to L.H,center&R.H, rear seats
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Notice** R.H. park brake could be improved
- Fail** Nearside Headlamp aim too low (1.8)

**MOT #5** 2012-02-28 14:24**MOT test number** 259889652048**Result** ✓ Passed

- Notice** Play in steering rack inner joint(s)
- Notice** O/s/f sill flange damaged
- Notice** Battery insecure
- Notice** Both front tyres worn outer edges, advise replace soon

**MOT #4** 2012-02-27 17:43**MOT test number** 537388352099**Result** ✗ Failed

- Notice** Battery insecure
- Notice** Both front tyres worn outer edges, advise replace soon
- Fail** Offside Rear coil spring fractured (2.4.C.1a)
- Notice** Play in steering rack inner joint(s)
- Notice** O/s/f sill flange damaged
- Fail** Front registration plate insecure (6.3.1b)

**MOT #3** 2011-01-20 16:34**MOT test number** 929330621007**Result** ✓ Passed**MOT #2** 2011-01-18 16:44**MOT test number** 759598511002**Result** ✗ Failed

- Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)



MOT #1	2010-01-20 10:28
MOT test number	850260020038
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-02-22
Last registration	2021-08-18
Complete history	<a href="#">See info</a>



Registration #1	2006-02-22	25 mi
Registration #2	2010-01-20	46.405 mi
Registration #3	2011-01-18	53.417 mi
Registration #4	2011-01-20	53.424 mi
Registration #5	2012-02-27	61.514 mi
Registration #6	2012-02-28	61.514 mi
Registration #7	2013-04-29	70.233 mi
Registration #8	2013-04-29	70.233 mi
Registration #9	2014-04-03	77.146 mi
Registration #10	2015-05-20	85.277 mi
Registration #11	2016-05-20	93.277 mi
Registration #12	2017-05-20	101.277 mi
Registration #13	2018-05-20	109.277 mi
Registration #14	2019-05-20	117.277 mi
Registration #15	2020-05-20	125.277 mi
Registration #16	2021-05-20	133.277 mi
Registration #17	2022-05-20	141.277 mi
Registration #18	2023-05-20	149.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2104 mm
Height	1782 mm
Length	4661 mm
Wheel base	2803 mm
Kerb weight	1755 kg
Max. allowed weight	2535 kg

Additional information

Fuel tank capacity	83 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	C042376